

0001



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

10274
gch

Norman H. Bangerter
Governor

Dee C. Hansen
Executive Director

Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 12/17/91
1:00-3:15

Permittee and/or Operator's Name: Andalex Resources, Inc.
Business Address: P.O. Box 902
Mine Name: Centennial Project Permit Number: ACT/007/019
Type of Mining Activity: Underground Surface Other
County: Carbon Company Official(s): Mike Glasson
State Officials(s): Sharon Falvey, Wayne Western
Federal Official(s): None
Partial: Complete Date of last Inspection: 11/26/91
Weather Conditions: Fair, Cool
Acreage: Permitted 4244 Disturbed 34 Regraded 0 Seeded 0
Bonded 34 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(x)	()	()	(x)
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	(x)	()	()	(x)
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	(x)	()	()	(x)
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION: 12/17/91

(Comments are Numbered to Correspond with Topics Listed Above)

4. Hydrologic Balance:
b. Diversions

Culverts associated with diversion ditches were clear and functioning. Sediment was gathered behind a straw bale at a point west of the haul road and north of the Lower Pinnacle Mine. The volume collected appeared to have the potential to jump the channel if the design event would occur. The operator cleared sediment from behind the bale while we continued the site inspection.

5. EXPLOSIVES

The Powder Magazine Area is locked and secure.

8. NONCOAL WASTE

A small oil and fuel storage structure is located on the north end of the pad at the Upper Pinnacle Portals. A small area of the pad has a fuel spill in approximately a 2 ft. radius. The operator indicated the affected area would be cleaned up. This was not identified as a problem area in the past, but should be monitored for frequency of spill occurrences.

Copy of this Report:

Mailed to: Bernie Freeman OSM, Mike Glasson-Andalex
Given to: Daron Haddock, Joe Helfrich, Wayne Western, DOGM

Inspector's Signature & Number: Shawn Feltus #38 Date: 12/20/91