

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/019 DATE OF INSPECTION: June 16, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

4a. Diversions -

The diversions were inspected and measured and to compared with the design requirements. The diversion did meet the performance standards as required in the R645 regulations. The operator will submit a new updated diversion map and a cross-sectioned diversion chart. This is to conform with the new regulation format.

4b. Sediment Ponds and Impoundments -

The sediment ponds were dry and no water was flowing into the ponds. There were no signs of erosion from the slope, inlets or outlets of the pond.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:


Mailed to: Andalex Resources, Mike Glasson

Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: June 23, 1993

Inspector's Signature and Number:  #39
Stephen J. Demczak