

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/019 DATE OF INSPECTION: February 16, 1993

(Comments are Numbered to Correspond with Topics Listed Above)

4a. Diversions -

The diversion ditches were covered with approximately 24" of snow. No ditches or culverts had water flow.

4b. Sediment Ponds and Impoundments -

The sediment ponds contained small amounts of water and were not discharging. The ponds have approximately 24" of snowfall on the embankments. Inlets and outlets from the ponds could not be seen due to the snow.

16b. Drainage Controls -

Snow was removed from the roadways and stacked in the appropriate places. When melting occurs it will drain into sediment ponds.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Andalex Resources, Mike Glasson

Mailed to: Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: March 4, 1993

Inspector's Signature and Number:


Stephen J. Demczak

#39