



INSPECTION REPORT  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/019

DATE OF INSPECTION: July 2, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

a) The operator is in the process of getting an approval for a new leased area for mining an additional seam of coal. Andalex Resources has the approval to mine an existing seam of coal in this leased area.

b) The longwall is planned to start-up the week of the 10th.

3. Topsoil Piles -

The topsoil pile at the crib storage area has small tree seeding planted as requested by the Division.

4a. Diversions -

Several disturbed diversions throughout the property have been re-graded since the last inspection. The ditches have not had water flow due to the dry summer. No performance problems were noted during the inspection.

4b. Sediment Ponds -

All sediment ponds were dry. There were no signs of erosion or instability to the ponds.


4c. Other Sediment Control Measures -

Many straw bales throughout the property have been replaced in the past few months. These areas are ASCA areas. These areas have may have adequate amount of vegetation to reclassify as small area exemptions. If the operator chooses to demonstrate to do so.

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Mike Glasson (Andalex) Bernie Freeman (OSM)  
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office  
Date: July 18, 1994

Inspector's Signature and Number:  #39  
Stephen J. Demczak