


007/019 #2

0009



ANDALEX
RESOURCES, INC.
Tower Division

P.O. BOX 902
PRICE, UTAH 84501
PHONE (801) 637-5385
TELECOPIER (801) 637-8860


February 5, 1996

MPD
Received
2/15/96
c
PFO

State of Utah
Department of Natural Resources
Division of Oil, Gas & Mining
355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203

Attn: Daron Haddock, Permit Supervisor

Re: ACT 007/019 - 94E



Dear Mr. Haddock:

Enclosed are responses to deficiencies outlined in your December 19, 1995, letter pertaining to the mid-term review. I must point out that several of the deficiencies outlined by your staff have clearly already been addressed. The updated material which you returned to ANDALEX along with the approval letter contains several of the items requested by your staff in the "requirements" section of the December 19 letter.

Permit Application:

- 1) D. Mathis has been deleted from the contiguous subsurface owners as this is an error, making Plate 3 correct. Zion Security is listed as a sub-surface owner within. Sunedco is listed as a surface and subsurface owner within and contiguous. Gladys Artman and the State of Utah are shown as surface owners within and contiguous .
- 2) The copy of Plate 4 which was returned to ANDALEX with the plan approval does not contain the phrase "Centennial Seam only."
- 3) See Plate 1.

State of Utah
Department of Natural Resources
Attn: Daron Haddock
February 5, 1996
Page Two

Notarized Statement:

- 1) See Page 9, R645-301-112.200

Resource Information:

- 1) The material which was returned to ANDALEX as approved contained a copy of lithologic log DH-1 with the hand-written note still attached indicating it was to be "for Appendix E".

Operational Plan:

- 1) See R645-301-522, Page 246.

Maps and Plans:

- 1) Plate 2 has never depicted surface disturbance; it is a surface ownership plate. Plate 5 does not cover the area where the fan is located, therefore, it was most logical to update Plate 1 which shows the entire disturbed area on one plate.

Hydrologic Information:

- 1) The reason that R645-301-731.511.4 states "N/A" is that it does not apply to ANDALEX. MSHA does not require an approval for discharge of water into the mine; therefore, it is not applicable.

Reclamation Plan:

- 1) Information on Pages 49-A and 49-B has not been deleted. It is in the copy returned to ANDALEX with the approval. Page 47 does not refer to topsoil redistribution over 33.5 acres. All references to anything but 34.2 acres were corrected in the last submittal.

State of Utah
Department of Natural Resources
Attn: Daron Haddock
February 5, 1996
Page Three

Geologic Information:

- 1) The discrepancy between R645-301-525.170 which states all monuments including subsidence monitoring stations will be reclaimed and R645-301-642 was resolved in our last submittal. R645-301-642 now states "See R645-301-525.170".
- 2) Page 355, R645-301-640 and -641 were corrected and highlighted in our last submittal. The information returned to ANDALEX with the approval contains this corrected page.

Revegetation:

- 1) Since ANDALEX cannot provide baseline information on areas previously disturbed, R645-301-356.250 does not apply and has been removed from R645-301-353.110.
- 2) See R645-301-353.110 through -250, previously submitted.
- 3) See R645-301-342.100.

Sincerely,



Michael W. Glasson
Senior Geologist

MWG/rr

cc: Lowell Braxton