

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		Page 1 of 1
Permit Number	C/007/020	Report Date: 5-15-03
Mine Name	Horizon	
Company Name	Hidden Splendor Resources, Inc.	
Impoundment Identification	Impoundment Number	001
	UPDES Permit Number	UTG040019
IMPOUNDMENT INSPECTION		
Inspection Date	5-14-03	
Inspected By	David B. Miller	
Reason for Inspection <small>(Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)</small>	Quarterly Inspection	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition. No signs of instability noted at this incised pond. There is no evidence of slumping in the pond or on the embankment. No hazardous conditions were noted.</p>		
Required for an impoundment which functions as a SEDIMENTATION POND.	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment. 60% Sediment Storage - 7566.9 100 % Sediment Storage - 7569.8</p>	
	<p>3. Principle and emergency spillway elevations. Spillway Elevation - 7573.9 Feet</p>	
	<p>4. Field Information The water level in the pond was approximately 1 to 1.5 feet in depth. The pond was not discharging at the time of inspection. No flow into the pond during the inspection. The inlets and outlet were stable. No instability was noted on the downstream embankment. All snow had melted around the pond.</p>	