

Attachment A photos August 20, 2018



PHOTO 1 Dozer pushing soil to West. Excavator perfecting 2h:1v slopes



PHOTO 2 Portal Cyn 2h:1 v slopes to be roughened



PHOTO 3 View S of Portal Cyn at location of buried portals



PHOTO 4 View up Portal Cyn taken at aspen at base of topsoil pile on E side

Attachment A photos August 20, 2018



PHOTO 5 Taken at pine tree on West side of topsoil pile.



PHOTO 6 UD inlet and topsoil stockpile above



PHOTO 7 Portal Cyn looking at W slope above UD inlet



PHOTO 8 Portal Cyn looking upstream and E slope above UD inlet

Attachment A photos August 20, 2018



PHOTO 9 Another shot of Steve pushing from the bottom and Dal finishing on top.



PHOTO 10 Taken from the top of the finished slopes to the east of the channel. These slopes are ready for roughening/topsoil placement.



PHOTO 11 The test pit in the bottom of the sed pond with 5' Priscilla for scale. It appears to be coal fines from top to bottom.



PHOTO 12 All of the machinery currently on site. Looking north from the paved county road.

Attachment A photos August 20, 2018



PANORAMA 1 Taken from a location on the hillside just south of the power poles. This gives a view of Steve and Dal finishing the channel emerging from portal Canyon on the right. The lower pad area is in the center, and the sediment pond is on the far left.



Panorama 2 Taken from the quaking aspen on the East slope at the base of the topsoil pile, showing Portal Canyon.