

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/021

DATE OF INSPECTION: 9/20/95

(Comments are Numbered to Correspond with Topics Listed Above)

4A. DIVERSIONS -

The diversions throughout the property were not functioning as designed; they are being filled with sediment and/or rock. In several places, the water was entering the stream without being treated.

4B. SEDIMENT PONDS -

The sediment pond was not discharging during the inspection. The pond appeared to have no hazardous conditions existing.

4C. OTHER SEDIMENT CONTROL MEASURES -

There are no straw bales or silt fences that are functioning as designed throughout the property. Therefore, all alternate sediment control areas are not being treated.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:


Mailed to: Donna Griffin (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: September 25, 1995

Inspector's Signature: _____


Stephen J. Demczak

#39