

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/021

DATE OF INSPECTION: 8/30/95

(Comments are Numbered to Correspond with Topics Listed Above)

4A. DIVERSIONS -

The diversions are not functioning as designed and have not been for several years. This situation will continue until the site is completely reclaimed. Management feels it is better to spend bond money on reclamation than maintenance. There is no immediate plans in the near future to reclaim this site to my knowledge.

4B. SEDIMENT PONDS AND IMPOUNDMENTS -

The sediment pond appeared to be stable and with no hazardous conditions existing. The pond was basically dry.

13. REVEGETATION -

Canadian thistle have started to infiltrate the property.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Donna Griffin (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: September 1, 1995

Inspector's Signature: _____

Stephen J. Demczak

#39