

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/021

DATE OF INSPECTION: 7/12/95

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMIT -

The Division is in the process of reclaiming the water well at the Blazon site. It seems to be a conflict with the landowner to access the site. Correspondence between the Division and landowner has taken place.

4A. DIVERSIONS -

The diversions remain filled with sediment and are not functioning as designed.

4B. SEDIMENT PONDS -

The sediment pond did contain a small amount of water. It is highly unlikely that the sediment pond would discharge this year. The pond appears to be stable with no hazardous conditions existing.

4C. OTHER SEDIMENT CONTROL MEASURES -

The straw bales and silt fences are not functioning as designed.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Donna Griffin (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: August 1, 1995

Inspector's Signature: _____

Stephen J. Demczak

#39