



**INSPECTION REPORT**  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/021

DATE OF INSPECTION: 5/29/96(REVISED)

(Comments are Numbered to Correspond with Topics Listed Above)

**4A. DIVERSIONS -**

This is the first time that the site could be visited since fall of 1995. This was due to the snow fall through the winter.

The diversions need to be regraded for them to function correctly. There are three ditches along the parameter to the property which needs to be cleaned out. It would take one backhoe or grader one-half day's work to correct this situation. The cost should be under \$1,000.

**4B. SEDIMENT POND -**

The site has one sediment pond which contained a small amount of water. Only a partial amount is entering the pond due to sediment build-up in these diversions cannot convey the total quantity of water.

**4C. OTHER SEDIMENT CONTROL MEASURES -**

All silt fences are non-functional. These may not be need if a demonstration was made by Division employees.

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Steve Tanner (Landowner)

Marcia Petta (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: June 20, 1996

Inspector's Signature: \_\_\_\_\_

Stephen J. Demczak  
Stephen J. Demczak

#39