



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangertter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Aug. 10, 1988
8:00-9:00 a.m.

Permittee and/or Operators Name: Beaver Creek Coal Co.
Business Address: P.O. Box 1378 Price, Utah 84501
Mine Name: C.V. Spur Permit Number: ACT/007/022 7035
Type of Mining Activity: Underground Surface Other XXX
County: Carbon State: Utah
Company Official(s): Dan Guy
State Official(s): Bill Warmack and John Whitehead
Partial: XX Complete: _____ Date of Last Inspection: June 28, 1988
Weather Conditions: Clear and warm
Acreage: Permitted 160 Disturbed 108 Regraded _____ Seeded _____ Bonded 160
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	(X)	()	()	(X)
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	(X)	()	()	(X)
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/022

DATE OF INSPECTION Aug. 10, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

Measurable amounts of precipitation have been absent from this area producing a very dry, harsh environment evidenced by the marginal plant growth throughout this site. Low-lying areas that can trap and hold the moisture, however, show some signs of strong plant growth.

2. SIGNS AND MARKERS:

Refuse fill sign was noted and in good repair.

4c. SEDIMENT PONDS AND IMPOUNDMENTS:

Ponds 1, 2, 3, 5 and 6 were observed; no associated erosion problems were noted. All the ponds, with the exception of #2, contained water.

4d. OTHER SEDIMENT CONTROL MEASURES:

The straw bales below the topsoil storage area adjacent to the refuse pile were in good repair.

7. COAL PROCESSING WASTE:

The refuse pile was well graded and compacted; no erosion had developed on the outslope banks.

13. REVEGETATION:

Plant growth in the test plot area is marginal; halogeton was observed throughout the area with sparse occurrences of grass. The plant site was very dry and evidence of lack of moisture was shown even in the halogeton areas.

16d. ROAD MAINTENANCE:

Due to the lack of moisture, the roads were being treated to alleviate the associated dust problems.

Copy of this Report:

Mailed to: Dan Guy, BCCC

Mailed to SLC for: Brian Smith, DSM; Joe Helfrich, DOGM

Filed to: PFO

Inspectors Signature and Number: William A. Warmack #30 Date: Aug. 12, 1988

William A. Warmack