

0002



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

Norman H. Bangarter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

Act 007/022

RVS  
gch

## INSPECTION REPORT

INSPECTION DATE & TIME: November 15, 1989  
11:00 a.m. to 12:30 p.m.

Permittee and/or Operators Name: Beaver Creek Coal Company  
Business Address: P.O. Box 1378, Price, Utah 84501  
Mine Name: C.V. Spur Permit Number: ACT/007/022  
Type of Mining Activity: Underground Surface X Other  
County: Carbon  
Company Official (s): Dan Guy  
State Official(s): Henry Sauer  
Partial X Complete:            Date of Last Inspection: Oct. 2, 1989  
Weather Conditions: Clear and Cool  
Acreage: Permitted 160 Disturbed 108 Regraded            Seeded            Bonded 108  
Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( X )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( X )
3. TOPSOIL	( )	( X )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( )	( X )	( )	( )
b. DIVERSIONS	( X )	( )	( )	( X )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( X )	( )	( )	( X )
d. OTHER SEDIMENT CONTROL MEASURES	( )	( X )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( X )	( )	( X )
f. EFFLUENT LIMITATIONS	( )	( X )	( )	( )
5. EXPLOSIVES	( )	( )	( X )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( X )	( )	( )
7. COAL PROCESSING WASTE	( )	( X )	( )	( )
8. NONCOAL WASTE	( )	( X )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( X )	( )	( )	( X )
10. SLIDES AND OTHER DAMAGE	( )	( X )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( X )	( )	( )
12. BACKFILLING AND GRADING	( )	( X )	( )	( )
13. REVEGETATION	( X )	( )	( )	( X )
14. SUBSIDENCE CONTROL	( )	( )	( X )	( )
15. CESSATION OF OPERATIONS	( )	( )	( X )	( )
16. ROADS				
a. CONSTRUCTION	( )	( X )	( )	( )
b. DRAINAGE CONTROLS	( X )	( )	( )	( X )
c. SURFACING	( )	( X )	( )	( )
d. MAINTENANCE	( )	( X )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( X )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( X )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 4

PERMIT NUMBER: ACT/007/022

DATE OF INSPECTION Nov. 15, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS
2. SIGNS AND MARKERS
3. TOPSOIL
4. HYDROLOGIC BALANCE
  - a. STREAM CHANNEL DIVERSIONS
  - b. DIVERSIONS
  - c. SEDIMENT PONDS AND IMPOUNDMENTS
  - d. OTHER SEDIMENT CONTROL MEASURES
  - e. SURFACE AND GROUNDWATER MONITORING
  - f. EFFLUENT LIMITATIONS
5. EXPLOSIVES
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL
- d. COAL PROCESSING WASTE
8. NONCOAL WASTE
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES
10. SLIDES AND OTHER DAMAGE
11. CONTEMPORANEOUS RECLAMATION
12. BACKFILLING AND GRADING
13. REVEGETATION
14. SUBSIDENCE CONTROL
15. CESSATION OF OPERATIONS
16. ROADS
  - a. CONSTRUCTION
  - b. DRAINAGE CONTROLS
  - c. SURFACING
  - d. MAINTENANCE
17. OTHER TRANSPORTATION FACILITIES
18. SUPPORT FACILITIES UTILITY INSTALLATIONS

: Copy of this Report:

Mailed to: John Kathman-OSM and Dan Guy, BCCC

Given to: Joe Helfrich-DOGM

Inspectors Signature and Number: #32

*Henry Lawrence*

Date: 11/20/89

**INSPECTION REPORT**  
(continuation sheet)

Page 3 of 4

PERMIT NUMBER: ACT/007/022

DATE OF INSPECTION Nov. 15, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

**General Comments**

Dan Guy (BCCC) accompanied the undersigned inspector on this partial state inspection of the loadout site. Weather conditions were clear and cool. There was no evidence of recent precipitation events.

**2. Signs and Markers:**

A new paved haul road has been constructed on site. The entrance to the facility is now located at the northwest corner of the permit area. Identification signs for the new entrance have not yet been constructed. Identification signs remain in place at the location of the old entrance gate.

**4. Hydrologic Balance:**

**4(b) Diversions**

All ditches and culverts were observed and appear to be in good repair and functioning properly.

**4(c) Sediment Pond and Impoundments**

Mr. Guy informed me that Sediment Pond #2 will be cleaned out in the near future.

Presently, BCCC is pumping water out of Sediment Pond #6, using it to water roads throughout the site.

**9. Protection of Fish, Wildlife and Related Environmental Values**

Perch guards for particular power poles are on order and will be constructed as soon as possible.

**16. Roads**

**16(b) Drainage Controls**

A small portion (1 foot wide) of the berm surrounding the Trail Mountain truck dump road has been breached by runoff. The operator was instructed to reconstruct this portion of the berm by the next inspection.

**INSPECTION REPORT**  
(continuation sheet)

Page 4 of 4

PERMIT NUMBER: ACT/007/022

DATE OF INSPECTION Nov. 15, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

**13. Revegetation**

The revegetation test plots have been constructed and are fenced. The operator was informed that an as-built description of the procedures and materials used to construct the test plots is required.

Additionally, both topsoil stockpiles have been deep ripped, hydroseeded and hydromulched.

djh  
AT43/57-60