



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

Joh pgl

INSPECTION REPORT

INSPECTION DATE & TIME: August 28, 1991
1:00 pm to 2:00 pm

Permittee and/or Operator's Name: Beaver Creek Coal (Mountain Coal Co)
Business Address: P.O. Box 1378, Price, Utah 84501
Mine Name: C.V. Spur Loadout Permit Number: ACT/007/022
Type of Mining Activity: Underground Surface Other X
County: Carbon Company Official(s): Burk Biersdorf
State Officials(s): Susan White
Federal Official(s): None
Partial: X Complete Date of last Inspection: July 18, 1991
Weather Conditions: Warm and fair
Acreage: Permitted-160 Disturbed-108 Regraded Seeded Bonded-108
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	(X)	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/022

DATE OF INSPECTION: 08/28/91

(Comments are Numbered to Correspond with Topics Listed Above)

4b. Diversions

The drainage off the northeast end of the refuse pile is eroding. A better solution to this drainage needs to be implemented.

4c. Sediment Ponds and Impoundments

Sediment ponds are in good condition and contain some water. Pond banks are free from rills and gullies and inlets are in good repair. Ponds are not discharging.

13. Revegetation

Little success on site from revegetation efforts was observed. Some of the best success in on the refuse pile test plots where soil and refuse has been mixed. I believe efforts should concentrate on establishing shrubs, which are similar to the surrounding undisturbed areas.

Copy of this Report:

Mailed to: Dan Guy (BCCC), John Kathmann (OSM)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: Susan M. White #35 Date: 09/04/91