

**2001 Annual Report**  
**Savage Coal Terminal**

**C/007/022**

**RECEIVED**

**APR - 1 2002**

**DIV OF OIL GAS & MINING**

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No 0007 Date 04/01/2002  
In C/007/022/2002 Submitting  
For additional information

0007

**COPY**

RECEIVED

APR 01 2002

DIVISION OF  
OIL, GAS AND MINING



Savage Industries Inc.  
2025 East 5000 South  
Price, Utah 84501

(435) 637-5664  
(435) 637-3418 Fax

March 27, 2001

Mr. Daron R. Haddock  
Permit Supervisor  
Utah Division of Oil, Gas & Mining  
1594 West North Temple, Suite 1210  
Box 145801  
Salt Lake City, Utah 84114-5801

*Incoming  
C/007/022*

Re: Annual Report for 2001  
Savage Coal Terminal  
C/007/022  
Carbon County, Utah

Dear Mr. Haddock:

Enclosed is one copy of the 2001 Annual Report for the Savage Coal Terminal. An additional report has been submitted to the Price Field Office.

If you need any additional information, please let me know.

Sincerely,

Dan W. Guy  
for  
Boyd Rhodes

cc: Price Field Office  
Boyd Rhodes - Savage  
File

*C/007/0022 2002 Incoming*

- Refer to:
- Confidential
- Shelf
- Expandable

Date *4/1/02* For additional information

**GENERAL INFORMATION**

1. Permit Number	C/007/022
2. Mine Name	Savage Coal Terminal
3. Permittee Name	Savage Industries, Inc.
4. Operator Name (if other than Permittee)	
5. Permit Expiration Date	August 07, 2004
6. Permit Number	C/007/022
7. Company Representative, Title	Boyd Rhodes, Manager
8. Phone Number	(435) 637-5664
9. Fax Number	(435) 637-3418
10. E-mail Address	
11. Mailing Address	Savage Industries, Inc. 5250 South 300 West Suite 200 Salt Lake City, Utah 84107
12. Resident Agent, Title	Corporation Trust Company
13. Mailing Address	Corporation Trust Company 1209 Orange Street Wilmington, DE 19801
14. Number of Binders Submitted	(2) 1- Salt Lake Office and 1- Price Field Office

**IDENTIFICATION OF OTHER PERMITS**

Identify other permits which are required in conjunction with mining and reclamation activities.

Permit Type	ID Number	Description	Expires on
1. MSHA Mine ID(s)	42-01444	Plant Loadout	N/A
2. MSHA Impoundment(s)	N/A		

2001 ANNUAL REPORT		Savage Coal Terminal		C/007/022	Page 2
3. NPDES/UPDES Permit(s) (water)	UTG-040005	UPDES Permit 06/01/98		04/30/03	
4. PSD (Air ) Permit(s)	DAQE-007-97	Approval Order		N/A	
5.					
6.					

### CERTIFIED REPORTS

List the certified inspection reports as required by the rules and under the approved plan which must be periodically submitted to the Division. Specify whether the information is included as APPENDIX A to this Annual Report or currently ON FILE with the Division.

Certified Reports:	Reports Required?		INCLUDED or ON FILE w/DOGM?		Comments
	YES	NO	Included	ON FILE	
1. Excess Spoil Piles		X			
2. Refuse Piles	X		X		Appendix A
3. Impoundments	X		X		Appendix A
4.					
5.					

### REPORTING OF OTHER TECHNICAL DATA

List other technical data and information as required under the approved plan which must be periodically submitted to the Division. Specify whether the information is included as APPENDIX B to this Annual Report or currently ON FILE with the Division.

Technical Data:	Reports Required?		INCLUDED or ON FILE w/DOGM?		Comments
	YES	NO	Included	ON FILE	
1. Climatological Data		X			
2. Subsidence Monitoring Data		X			
3. Vegetation Monitoring Data	X		X		Appendix B
4. Raptor Survey		X			
5. Soils Monitoring Data		X			
6. Water Monitoring Data	X			X	

2001 ANNUAL REPORT		Savage Coal Terminal			C/007/022	Page 3
First Quarter Report	X			X		
Second Quarter Report	X			X		
Third Quarter Report	X			X		
Fourth Quarter Report	X			X		
7. Geological/Geophysical Data		X				
8. Engineering Data		X				
9. Other Data						

**LEGAL, FINANCIAL, COMPLIANCE AND RELATED INFORMATION**

Changes in administration or corporate structure can often bring about necessary changes to information found in the mining and reclamation plan. The Division is requesting that each permittee review and update the legal, financial, compliance and related information in the plan as part of the Annual Report. Provide the Department of Commerce, Annual Report of Officers, or other equivalent information as necessary to ensure that the information provided in the plan is current. Provide any other changes as necessary regarding land ownership, lease acquisitions, legal results from appeals of violations, or other changes as necessary to update information required in the mining and reclamation plan. Include any certified financial statements, audits or worksheets which may be required to meet bonding requirements. Specify whether the information is currently ON FILE with the Division or included as APPENDIX C to this Annual Report.

Legal/Financial Data:	Report Required?		INCLUDED or ON FILE w/DOGM?		Comments
	YES	NO	Included	ON FILE	
1. Department of Commerce, Annual Report of Officers	X			X	
2. Other					

**MINE MAPS**

Copies of mine maps, current and up-to-date through at least December 31, 1998, are to be provided to the Division as APPENDIX D to this Annual Report in accordance with the requirements of R645-301-525.270. These map copies shall be made in accordance with 30 CFR 75.1200, as required by MSHA. Upon request, mine maps shall be kept confidential by the Division.

Map Number(s)	Map Title / Description	Confidential?
N/A		

# **APPENDIX A**

## **Certified Reports**

Excess Spoil Piles  
Refuse Piles  
Impoundments

as required under R645-301-514

### **CONTENTS**

## **Refuse Pile Inspections and Annual Impoundment Inspections**

## SAVAGE COAL TERMINAL REFUSE PILE INSPECTION REPORT

MSHA SITE:           \*1211-UT-09-01444-01           QUARTER:           04/2001          

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Slopes appear stable.
(3) Removal of Topsoil/Organics.	Refuse Pile being removed from West End.
(4) Construction and Maintenance Performance Standards.	Top of pile graded - Berm is O.K. Culvert Relocated - O.K. Ditches - O.K. Pile being removed from west end for Sunnyside Cogeneration.
(5) Recommendations/Comments.	Sign/ID # changed to 1211-UT-09-01444-01.

*I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.*



*Dan W. Guy*

(Signature)

11/28/01

(Date)

\* Re-assigned ID Number - Old Number (1211-UT-09-0034)

## SAVAGE COAL TERMINAL REFUSE PILE INSPECTION REPORT

MSHA SITE:           \*1211-UT-09-01444-01           QUARTER:           03/2001          

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Slopes appear stable.
(3) Removal of Topsoil/Organics.	Refuse Pile being removed from West End.
(4) Construction and Maintenance Performance Standards.	Top of pile graded - Berm is O.K. Culvert Relocated - O.K. Ditches - O.K. Pile being removed from west end for Sunnyside Cogeneration.
(5) Recommendations/Comments.	Sign/ID # changed to 1211-UT-09-01444-01.

*I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.*



  
 \_\_\_\_\_  
 (Signature)

\_\_\_\_\_  
 09/25/01  
 (Date)

\* Re-assigned ID Number - Old Number (1211-UT-09-0034)

## SAVAGE COAL TERMINAL REFUSE PILE INSPECTION REPORT

MSHA SITE:           \*1211-UT-09-01444-01                QUARTER:           02/2001          

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Slopes appear stable.
(3) Removal of Topsoil/Organics.	Refuse Pile being removed from East End.
(4) Construction and Maintenance Performance Standards.	Top of pile graded - Berm is O.K. Culvert Relocated - O.K. Ditches - O.K. Pile being removed from east end for Sunnyside Cogeneration.
(5) Recommendations/Comments.	Sign/ID # changed to 1211-UT-09-01444-01.

*I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.*



  
 \_\_\_\_\_  
 (Signature)

06/29/01  
 \_\_\_\_\_  
 (Date)

\* Re-assigned ID Number - Old Number (1211-UT-09-0034)

**SAVAGE COAL TERMINAL  
REFUSE PILE INSPECTION REPORT**

MSHA SITE:           \*1211-UT-09-01444-01           QUARTER:           01/2001          

ITEM	REMARKS
(1) Potential Safety Hazards	None Noted.
(2) Slope Stability	Slopes appear stable.
(3) Removal of Topsoil/Organics.	Refuse Pile being removed from West End.
(4) Construction and Maintenance Performance Standards.	Top of pile graded - Berm is O.K. Culvert Relocated - O.K. Ditches - O.K. Pile being removed from west end for Sunnyside Cogeneration.
(5) Recommendations/Comments.	Sign/ID # changed to 1211-UT-09-01444-01.

*I have performed the above inspection on this refuse pile and do hereby certify it to be a true and accurate representation of the pile at this time.*



*Dan W. Guy*  
\_\_\_\_\_  
(Signature)

03/22/01  
\_\_\_\_\_  
(Date)

\* Re-assigned ID Number  
Old Number (1211-UT-09-0034)

**SAVAGE INDUSTRIES, INC.**  
**2001 ANNUAL POND INSPECTION REPORT**

**POND:** Sediment Pond 1

**LOCATION:** Savage Coal Terminal

IMPOUNDMENTS	
(1) Stability	Slopes Stable. Incised Pond
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	3.0' Water.
(5) Existing Storage Capacity	0.90 acre feet.
(6) Monitoring Procedures	Quarterly Inspection.

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	5486.00
(8) Sediment Cleanout Level (Elevation)	5487.20
(9) Principle Spillway (Elevation)	5491.80
(10) Emergency Spillway (Elevation)	5491.80
(11) Existing Sediment Capacity (To Cleanout)	0.44 acre feet.

GENERAL	
(12) Comments/Recommendations	Pond O.K. No Discharge.

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

  
 (Signature)

11/28/01  
 (Date)



**SAVAGE INDUSTRIES, INC.**  
**2001 ANNUAL POND INSPECTION REPORT**

**POND:** Sediment Pond 2

**LOCATION:** Savage Coal Terminal

IMPOUNDMENTS	
(1) Stability	Slopes Stable. Incised Pond
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	Dry.
(5) Existing Storage Capacity	0.95 acre feet.
(6) Monitoring Procedures	Quarterly Inspection.

SEDIMENT PONDS DATA	
(7) Sediment Accumulation (Elevation)	5484.46
(8) Sediment Cleanout Level (Elevation)	5485.50
(9) Principle Spillway (Elevation)	5492.30
(10) Emergency Spillway (Elevation)	5492.30
(11) Existing Sediment Capacity (To Cleanout)	0.21 acre feet.

GENERAL	
(12) Comments/Recommendations	No Discharge.

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

  
 \_\_\_\_\_  
 (Signature)

11/28/01  
 \_\_\_\_\_  
 (Date)



**SAVAGE INDUSTRIES, INC.**  
**2001 ANNUAL POND INSPECTION REPORT**

**POND:** Sediment Pond 3

**LOCATION:** Savage Coal Terminal

IMPOUNDMENTS	
(1) Stability	Slopes Stable. Incised Pond
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	Dry.
(5) Existing Storage Capacity	0.91 acre feet.
(6) Monitoring Procedures	Quarterly Inspection.

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	5483.93
(8) Sediment Cleanout Level (Elevation)	5484.80
(9) Principle Spillway (Elevation)	5491.40
(10) Emergency Spillway (Elevation)	5491.40
(11) Existing Sediment Capacity (To Cleanout)	0.17 acre feet.

GENERAL	
(12) Comments/Recommendations	No Discharge.

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

  
 \_\_\_\_\_  
 (Signature)

11/28/01  
 \_\_\_\_\_  
 (Date)



**SAVAGE INDUSTRIES, INC.**  
**2001 ANNUAL POND INSPECTION REPORT**

**POND:** *Plant Overflow (#4)*

**LOCATION:** *Savage Coal Terminal*


IMPOUNDMENTS	
(1) <i>Stability</i>	<i>Slopes Stable. Incised Pond</i>
(2) <i>Structural Weakness/Erosion</i>	<i>None Noted.</i>
(3) <i>Potential Safety Hazards</i>	<i>None Noted.</i>
(4) <i>Depth of Impounded Water</i>	<i>3.5' Water (@ overflow).</i>
(5) <i>Existing Storage Capacity</i>	<i>0.00 acre feet.</i>
(6) <i>Monitoring Procedures</i>	<i>Not a sediment pond. Quarterly Inspection.</i>

SEDIMENT POND ONLY	
(7) <i>Sediment Accumulation (Elevation)</i>	<i>N/A</i>
(8) <i>Sediment Cleanout Level (Elevation)</i>	<i>N/A</i>
(9) <i>Principle Spillway (Elevation)</i>	<i>N/A</i>
(10) <i>Emergency Spillway (Elevation)</i>	<i>N/A</i>
(11) <i>Existing Sediment Capacity (To Cleanout)</i>	<i>N/A</i>

GENERAL	
(12) <i>Comments/Recommendations</i>	<i>Overflow to sediment pond 6 - then recirculated.</i>

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

  
 \_\_\_\_\_  
 (Signature)

\_\_\_\_\_  
 11/28/01  
 (Date)



**SAVAGE INDUSTRIES, INC.**  
**2001 ANNUAL POND INSPECTION REPORT**

**POND:** Sediment Pond 5

**LOCATION:** Savage Coal Terminal


<b>IMPOUNDMENTS</b>	
(1) Stability	Slopes Stable. Incised Pond
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	1.5' Water.
(5) Existing Storage Capacity	3.59 acre feet.
(6) Monitoring Procedures	Quarterly Inspection.

<b>SEDIMENT PONDS ONLY</b>	
(7) Sediment Accumulation (Elevation)	5473.80
(8) Sediment Cleanout Level (Elevation)	5475.20
(9) Principle Spillway (Elevation)	5482.00
(10) Emergency Spillway (Elevation)	5482.00
(11) Existing Sediment Capacity (To Cleanout)	0.46 acre feet.

<b>GENERAL</b>	
(12) Comments/Recommendations	No Discharge.

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

  
 \_\_\_\_\_  
 (Signature)

11/28/01  
 \_\_\_\_\_  
 (Date)



**SAVAGE INDUSTRIES, INC.**  
**2001 ANNUAL POND INSPECTION REPORT**

**POND:** Sediment Pond 6

**LOCATION:** Savage Coal Terminal

IMPOUNDMENTS	
(1) Stability	Slopes Stable. Incised Pond
(2) Structural Weakness/Erosion	None Noted.
(3) Potential Safety Hazards	None Noted.
(4) Depth of Impounded Water	4.0' Water.
(5) Existing Storage Capacity	1.01 acre feet.
(6) Monitoring Procedures	Quarterly Inspection. U.P.D.E.S. Discharge.

SEDIMENT PONDS ONLY	
(7) Sediment Accumulation (Elevation)	5473.60
(8) Sediment Cleanout Level (Elevation)	5474.70
(9) Principle Spillway (Elevation)	5480.30
(10) Emergency Spillway (Elevation)	5480.30
(11) Existing Sediment Capacity (To Cleanout)	0.22 acre feet.

GENERAL	
(12) Comments/Recommendations	No Discharge.

**STATEMENT**

*I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meets or exceeds the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.*

  
 \_\_\_\_\_  
 (Signature)

11/28/01  
 \_\_\_\_\_  
 (Date)



# **APPENDIX B**

## **Reporting of Technical Data**

including monitoring data, reports, maps, and other information  
as required under the approved plan  
or as required by the Division

in accordance with the requirements of R645-301-130 and R645-301-140.

### **CONTENTS**

## **Final Results - Revegetation Test Plot No. 1**

**FINAL RESULTS  
OF THE C.V. SPUR NO.1  
REVEGETATION TEST PLOTS**



Prepared by

***MT. NEBO SCIENTIFIC, INC.***

330 East 400 South, Suite 6

Post Office Box 337

Springville, Utah 84663

(801) 489-6937

for

***BLACKHAWK ENGINEERING***

Route 1, Box 146-H5

Helper, Utah 84526

by

Patrick Collins, Ph.D.

March 2001

## TABLE OF CONTENTS

SUMMARY .....	1
INTRODUCTION .....	1
Objectives .....	1
Location .....	2
Design .....	2
RESULTS & DISCUSSION .....	3
Cover .....	3
Composition .....	4
Density .....	5

FINAL RESULTS  
OF THE C.V. SPUR NO. 1  
REVEGETATION TEST PLOTS

SUMMARY

A test plot was constructed in 1987 that compared revegetation techniques including soil cover, coal refuse cover, wood fiber mulch, straw mulch and strip planting methods. Living cover data suggests the subplots that had more coal refuse performed better. Although the trend is not as evident for woody species density, data also suggests that density was greater in those plots with more coal refuse.

INTRODUCTION

Objectives

The purpose of this report is to summarize the final results of the Revegetation Test Plots at the C.V. Spur. No. 1 site. Although the plots have been monitored since their construction in 1987, the information herein was based on the most recent intensive quantitative vegetation sampling which was conducted in 1997.

Because this report is intended to be a 'summary' of the final results, all data tables, sampling methodologies, color photographs, and raw data *have not been included in the report*. A more complete set of this information can be found in the report called: VEGETATION MONITORING OF THE C.V. SPUR TEST PLOTS: 1997.

## Location

The C.V. Spur area is located approximately 4 miles southeast of the city of Price, Utah. The area is comprised of nearly 120 acres of disturbed land associated with coal cleaning and loading activities. The disturbed area lies within a salt desert community on soils derived from Mancos Shale.

## Design

Revegetation test plots investigating different treatments were established in the fall of 1987 by the former owner, Beaver Creek Coal Company. The entire research plot size is approximately 120 ft by 140 ft. This area was divided into sixteen 25 ft by 25 ft plots or "subplots" to test and compare different reclamation treatments. The treatments consisted of controls, topsoil depths, coarse refuse mixtures and mulches. More specifically, the treatments investigated with their respective subplot numbers are listed below on Table 1.

<b>SUBPLOT NUMBERS</b>	<b>TREATMENT</b>
1, 9	6 in. soil, seed, (control)
2, 6	6 in. soil, seed, wood fiber mulch
3, 7	4 in. soil, 2 in. coal refuse, seed, wood fiber mulch
4, 8	3 in. soil, 3 in. coal refuse, seed, wood fiber mulch
5	6 in. soil, wood fiber mulch, (strip planting)
10, 14	6 in. soil, seed, hay mulch
11, 15	4 in. soil, 2 in. coal refuse, seed, hay mulch
12, 16	3 in. soil, 3 in. coal refuse, seed, hay mulch
13	6 in. soil, hay mulch, (strip planting)

## RESULTS & DISCUSSION

Rather than providing all data summary tables with their respective data sets, graphs have been included in this report that facilitates comparisons of the final results. The graphs provided show results of all subplots for living cover, composition and woody species density.

### Cover

The living cover for each subplot has been illustrated in two ways. First, the data were summarized and comprised all

species, including the exotic

annuals or “weedy” species.

However, because weeds are not

considered to be desirable species

for final revegetation success, the

data also were summarized by

means that excluded these species.




Figure 1 graphically illustrates the total cover – with and without the weedy species.

Another way to represent and simplify the data was to combine the subplots that had identical treatments. This was done by averaging their values, thus deriving one value for each treatment instead of two (each treatment was replicated two times). For example, Subplot numbers 2 and 6

were the same treatment (6" in. soil, seed, wood fiber). Their cover values excluding weeds were 16.67% and 19.17%, respectively. The mean cover for this treatment would then be 17.92%.


The mean cover values of each treatment is shown on Figure 2.

Interestingly, the two highest cover values (Subplots 12/16 & 4/8) had the same seedbed medium

(3" soil, 3" coal refuse). The next highest cover also had similar growth medium (4" soil, 2" coal refuse).

Conversely, the subplots that performed with the least success for living cover were the subplots that had 6 inches of soil with no coal refuse added (Subplots 1/9, 5 & 13).


Fig. 2: MEAN COVER OF EACH TREATMENT  
C.V. Spur No 1 (1997)



Composition

Lifeform or species composition has also been graphically shown for each subplot for comparison. This provides the reviewer with information about the relative

Fig. 3: LIFEFORM COMPOSITION  
C.V. Spur No. 1 (1997)



cover proportion of shrubs, forbs and grasses. The graph is shown on Figure 3, but weedy species were included with the forbs.

### Density

Like the cover data described above, woody species density was also combined by treatments and shown on Figure 4. Woody species density also revealed interesting results and patterns. If one considers the subplots with the

wood fiber mulch, for example,

most subplots had high density

values, especially those that also

had coal refuse cover (Subplots

2/6, 3/7, & 4/8). The trend for the

hay mulch is that density increased


as coal refuse cover increased

(Subplots 10/14, 11/15 & 12/16).

Like the cover data, the subplots that performed poorest were those with the most soil cover

(Subplots 5, 13, & 1/9).

Fig. 4: MEAN DENSITY OF EACH TREATMENT  
C.V. Spur No. 1 (1997)



# **APPENDIX C**

## **Legal, Financial, Compliance and Related Information**

### **Annual Report of Officers**

as submitted to the Utah Department of Commerce

and other changes in ownership and control information  
as required under R645-301-110.

**CONTENTS**

**On File**

# **APPENDIX E**

## **Other Information**

in accordance with the requirements of R645-301 and R645-302.

**CONTENTS**

**N/A**