



0005

STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

John *John*
Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Oct. 22, 1987
8:00 a.m. to

Permittee and/or Operators Name: Andalex Resources Inc.
Business Address: P.O. Box 902 Price, Utah 84501
Mine Name: Wildcat Prep Plant Permit Number: PRO/007/033
Type of Mining Activity: Underground Surface Other X
County: Carbon
Company Official (s): Mike Glasson, John Pappas
State Official(s): Bill Malencik, Harold Sandbeck, DOGM; Joe Funk, OSM
Partial: Complete: X Date of Last Inspection: Oct. 13, 1987
Weather Conditions: Clear, warm, dry site
Acreage: Permitted Disturbed 60 Regraded Seeded Bonded
Enforcement Action: TDN 87-02-006-014 TV 1 (erosion diversion ditch)

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	(X)	()	()	(X)
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	(X)	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	(X)	()
7. COAL PROCESSING WASTE	(X)	()	()	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	()	()	(X)	()
12. BACKFILLING AND GRADING	()	()	(X)	()
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	(X)	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 3

PERMIT NUMBER: PRO/007/033

DATE OF INSPECTION Oct. 22, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

1. PERMITS:

Company is currently preparing information to submit a formal application to DOGM on or before December 31, 1987. Mr. Funk, OSM, was concerned that the company did not have an active permit. He discussed the matter with his management. The conclusion reached among OSM officials was that no OSM enforcement action would be taken. Also, The matter would be discussed further the following week and a required action, if any, would be decided at that time.

4b. DIVERSIONS:

State NOV 87-26-8-2, 2 of 2 was issued October 21, 1987, and abatement is due November 20, 1987, for violating performance standard on numerous culverts and problems relating to plugging inlet and outlet erosion protection. The aforementioned NOV was issued in conjunction with a prior partial inspection.

TDN 87-02-006-014, 1 of 1 was issued for erosion on a diversion that terminates in sediment pond E. The diversion drains in a southerly direction. At the upper end, sediment deposition is taking place; at the lower end, some erosion is evident. The company has placed straw bales to slow down the flow and cutting action, but it is not very effective. The diversion needs to be regraded and stabilized.

4c. SEDIMENT PONDS:

In the prior partial inspection, state NOV 87-26-8-2, 1 of 2 was issued for not conforming to UMC performance standards. The abatement is to be completed by November 20, 1987.

Copy of this Report:

Mailed to: Mike Glasson, Andalex (10-30-87); Brian Smith, OSM

Given to: Joe Helfrich, DOGM

Inspectors Signature and Number: Bill Malencik #26 Date: Oct. 30, 1987

INSPECTION REPORT
(continuation sheet)

Page 3 of 3

PERMIT NUMBER: PRO/007/033

DATE OF INSPECTION Oct. 22, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

Pond problems are as follows, as specifically noted in the previous inspection:

1. All ponds need certification.
2. Five ponds need an emergency spillway.
3. Some pond inlets need protection.
4. Some pond outlets need protection.
5. Most of the embankments need to be mulched and reseeded and some slope stabilization measures taken.

One piping hole on sediment pond D embankment needs to be repaired and was also listed in the aforementioned TDN.

16. ROADS MAINTENANCE:

A question exists where the southerly line shall be designated in the final permit approval in relation to the BLM/ROW fence. The operator stated the permit line will be designated within the fenced area currently following disturbed area perimeter markers. He said he would repair promptly the piping holes on the road shoulder and adjacent embankment that are currently outside the disturbed area and outside of his intended permit boundary.

Inspectors Signature and Number: Bill Malencik #26 Date: Oct. 30, 1987