



0013
 STATE OF UTAH
 NATURAL RESOURCES
 Oil, Gas & Mining

RE
 7-20-87

John

J. Bangerter

Norman H. Bangerter, Governor
 Dee C. Hansen, Executive Director
 Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: July 6, 1987
2:00 p.m. to 4:30 p.m.

Permittee and/or Operators Name: Andalex Resources, Inc.
 Business Address: P.O. Box 902 Price, Utah 84501
 Mine Name: Wildcat Loadout and Prep Plant Permit Number: PRO/007/033
 Type of Mining Activity: Underground Surface Other
 County: Carbon
 Company Official (s): Charles Adelege
 State Official(s): Wm. J. Malencik
 Partial: Complete: Date of Last Inspection: June 12, 1987
 Weather Conditions: Clear/Warm
 Acreage: Permitted 37 Disturbed 37 Regraded 37 Seeded 37 Bonded 37
 Enforcement Action: None; preventative maintenance: items C, 2, 4c, and 6b.

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	(X)	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	()	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	()	()	(X)	()
12. BACKFILLING AND GRADING	()	()	(X)	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	(X)
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: PRO/007/033

DATE OF INSPECTION July 6, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

FOLLOW-UP TO PREVIOUS INSPECTIONS:

- A. Road resurfacing completed; no problems, looks good.
- B. Sediment pond inlets, straw bales installed, needs more preventative maintenance work. See comments below.
- C. New signs have not yet been installed as mentioned in inspection report dated May 22, 1987. These are the primary identifying signs changing the name from Tower Resources to Andalex Resources, Inc. By copy of this report, Mike Glasson is requested to provide a progress report on this item by phone to the undersigned.

2. SIGNS AND MARKERS:

Sign could not be located on sediment pond A. Also, topsoil sign between sediment pond A and B needs maintenance.

4c. SEDIMENT PONDS:

Inlets to the sediment ponds C, D, and E need to be rip-rapped. Coal refuse boney has been utilized in some inlet channels and is unsatisfactory material as pointed out in DOGM letter to Mr. Glasson of June 9, 1987. This letter also pointed out that the proposed sediment pond monitoring changes are contingent on installing appropriate rip-rapping in the sediment pond inlet channels. The letter also requests detail plans be submitted to DOGM. Any questions concerning the designs and/or plan should be addressed to DOGM hydrologist, J. R. Fricke.

6b. ROAD DRAINAGE CONTROL:

Upper road drain ditch immediately above sediment pond B needs to be cleaned. The runoff is not currently crossing the road, but exiting the culvert and thence into sediment pond B. However, preventative maintenance is needed because succeeding storms may result in runoff topping the road.

Copy of this Report:

Mailed to: Mike Glasson, Andalex Resources; Donna Griffin, OSM

Given to: Joe Helfrich

Inspectors Signature and Number: Wm. J. Malencik #26 Date: July 6, 1987