

0020

RE 4-7-87

[Handwritten signature]

SCJ JOK



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangarter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 03/31/87
9:40 - 11:45

Permittee and/or Operators Name: Andalex Resources, Inc. (ARI)
Business Address: P.O. Box 902, Price, UT. 84501
Mine Name: Wildcat Loadout Permit Number: PRO/007/033
Type of Mining Activity: Underground Surface Other XX Prep Plant
County: Carbon
Company Official (s): John Pappas
State Official(s): James Leatherwood
Partial: XX Complete: Date of Last Inspection: 02/04/87
Weather Conditions: Sunny, mild
Acreage: Permitted Disturbed 37 Regraded Seeded Bonded
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	()	()	()	()
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	(X)
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: PRO/007/033

DATE OF INSPECTION 03/31/87

(Comments are Numbered to Correspond with Topics Listed Above)

4.b. Diversions:

The roads and diversions were being regraded at the time of inspection. The drainage diversion from the gate south to and around the weigh station connects to another diversion which flows to sediment pond A. During the recent regrading activities the junction between these two drainages was partially obstructed with soil. I explained to the operator that this junction must be cleared out. Mr. Pappus said he would get on it right away. There was no active runoff and the junction was not inundated beyond working capability.

4.c. Sediment Ponds and Impoundments:

All five sediment ponds were inspected. There was no evidence of any stability or erosion problems. No water was impounded. Operators last date of sediment pond inspection was 3/16/87.


9. Protection of Fish, Wildlife and Related Environmental Values:

All of ARI's powerlines were inspected. All lines are similar to the drawing submitted March 10, 1987 by Mike Glassen of ARI. The March 10, 1987 response to the Divisions Feb. 18, 1987 directive adequately documents that the powerlines under ARI's control were constructed according to acceptable raptor protection technology.

Copy of this Report:

Mailed to: John Pappas

Given to: Joe Helfrich, Sue Ligner

Inspectors Signature and Number:  #16 Date: 04/07/87