



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

PRO/007/083  
Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

June 9, 1987

Mr. Michael W. Glasson  
Senior Geologist  
Andalex Resources, Inc.  
Tower Division  
P.O. Box 902  
Price, Utah 84501

Dear Mr. Glasson:

Re: Technical Review, PAP Amendment, Request to Change Sediment Pond  
Inspection Frequency, Wildcat Loadout Facility, Andalex Resources, Inc.,  
PRO/007/033-87A, Folder #2, Carbon County, Utah

The Division has completed its review of Andalex Resources above referenced request for change received April 30, 1987. The request has been reviewed by reclamation hydrologist James Fricke, and cannot be approved at this time. Please refer to the attached Technical Memorandum to File for an explanation of the additional information which must be addressed before the Division can consider approving this request.

Please provide at least ten (10) copies of the revised plans and maps by July 3, 1987 to allow the Division to continue with the amendment review and approval process. Please call me, John Whitehead, or James Fricke, should you have questions or concerns with this review.

Sincerely,

D. Wayne Hedberg  
Data Management Coordinator

djh

Enclosure

cc: P. Rutledge      J. Leatherwood  
    R. Hagen         S. Linner  
    L. Berggren      P.F.O.  
    L. Braxton

8992R-51

May 18, 1987

TO: Coal File

FROM: James R. Fricke, Reclamation Hydrologist *JRF*

RE: Sediment Pond Stability Inspection, Andalex Resources, Andalex Mine, Wildcat Loadout, PRO/007/032, Folder #2, Carbon County, Utah

The operator has requested an amendment to the weekly sediment pond stability inspections. Before approval is granted, the following items should be addressed.

1. Several ponds have eroded inlets. The inlets should be repaired and erosion protection provided.
2. The operator has used coal refuse (bone) as erosion protection at the main pond. The Division does not find this material suitable as riprap.
3. The southwest pond has a slightly eroded bank; this should be repaired.

The operator should submit detailed plans for the mitigation of the above items. A site map with the ponds identified should accompany the erosion protection plan.

djh  
cc: J. Whitehead  
0798R/15