

0024



State of Utah
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

Handwritten signature

Michael O. Leavitt
Governor
Ted Stewart
Executive Director
James W. Carter
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340
801-359-3940 (Fax)
801-538-5319 (TDD)

Partial: X Complete: \_\_\_ Exploration: \_\_\_
Inspection Date & Time: 1/21/94 8am to 10am
Date of Last Inspection: 12/29/93

Mine Name: Wildcat Loadout County: Carbon Permit Number: ACT/007/033
Permittee and/or Operator's Name: Andalex Resources, Inc.
Business Address: P.O. Box 902, Price, Utah 84501
Type of Mining Activity: Underground \_\_\_ Surface \_\_\_ Prep. Plant X Other \_\_\_
State Official(s): Susan White
Company Official(s): Mike Glasson
Federal Official(s): None

Weather Conditions: Fair and unseasonably warm for January
Existing Acreage: Permitted- 100 Disturbed- 60 Regraded- \_\_\_ Seeded- \_\_\_ Bonded- 100
Increased/Decreased: Permitted- \_\_\_ Disturbed- \_\_\_ Regraded- \_\_\_ Seeded- \_\_\_ Bonded- \_\_\_
Status: \_\_\_ Exploration/ \_\_\_ Active/ X Inactive/ \_\_\_ Temporary Cessation/ \_\_\_ Bond Forfeiture
Reclamation ( \_\_\_ Phase I/ \_\_\_ Phase II/ \_\_\_ Final Bond Release/ \_\_\_ Liability \_\_\_ Year)
REVIEW OF PERMIT, PERFORMANCE STANDARDS & PERMIT CONDITION REQUIREMENTS

Instructions

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
a. For complete inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check N/A.
b. For partial inspections check only the elements evaluated.
2. Document any noncompliance situation by referencing the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Division Orders, and amendments.

Table with 5 columns: Item, EVALUATED, N/A, COMMENTS, NOV/ENF. Contains 21 rows of inspection items with checkboxes.

## INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/033

DATE OF INSPECTION: 1/21/94

(Comments are Numbered to Correspond with Topics Listed Above)

### 2. SIGNS AND MARKERS

The placement of disturbed area markers needs to be reevaluated. Currently, marker placement on the east side leaves one with the impression that the disturbed area borders the fence. However, looking at the disturbed area map this assumption is not correct.

The topsoil sign on the west pile need replacing.

### 4. HYDROLOGIC BALANCE:

A. **DIVERSIONS**- The straw bales in BTCA area 4 require replacement. Most disturbed diversions on the property had been recently reworked.

### 13. REVEGETATION

The 1993 test plots were being prepared. The operator was informed that due to seed dormancy requirements the seeding had to be completed by the end of the month. The test plots had been somewhat roughened and water catchment basins formed. The operator was encouraged to exaggerate this idea by making larger basins and roughness.

The revegetation test plots should have T posts placed at each corner.

### 20. AIR QUALITY

Coal fines are becoming a problem in the west, southwest portion of the property. Given a 30-year operational period and proposals to expand the coal pile, the operator must develop a plan to deal with this problem.

Copy of this Report:

Mailed to: Bernie Freeman (OSM), Mike Glasson (WCL)

Given to: Joe Helfrich (DOGM)

Inspector's Signature:

Susan M. White #35 Date: 1/25/94