

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/033

DATE OF INSPECTION: 6/6/96

(Comments are Numbered to Correspond with Topics Listed Above)

4A. DIVERSIONS -

The diversions were spot-checked throughout the property. The ditches were dry and contained little or no sediment within them. The diversions appeared to have been cleaned out recently.

4b. SEDIMENT PONDS -

The sediments pond were inspected and contained no water. The ponds are unlikely to discharge this summer due to the lack of sufficient rainfall. There were no evidences of erosion to these structure.

4C. OTHER SEDIMENT CONTROL MEASURES -

Several alternate sediment control locations were inspected. The operator uses straw bales as the sediment control measure. The ASCA areas were functioning as designed.

16. ROADS -

The main haul roads were starting to become dusty and additional watering of the these roads should be considered.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Mike Glasson (Andalex)

Marcia Petta (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: June 10, 1996

Inspector's Signature: _____


Stephen J. Demczak

#39