



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

INSPECTION REPORT

gh *DR7*

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

PERMIT NO.: ACT/007/034
Inspection Date: Nov. 14, 1990

Permittee and/or Operators Name: Soldier Creek Coal Co./Savage Coal
Business Address: P.O. Box I
City: Price State: Utah Zip: 84501
Mine Name: Banning Load Out
County: Carbon State: Utah
Type of Mining Activity: Underground Surface Other XX
Company Official (s): Johnny Pappas
State Officials (s): Stephen J. Demczak
Time of Inspection: 10:30 (X)a.m. ()p.m. to 11:45 (X)a.m. ()p.m.
Partial XX Complete: _____ Date of Last Inspection: _____
Weather Conditions: Clear/Mild
Acreage: Permitted 36 Disturbed 26.1 Regraded _____ Seeded _____ Bonded 21.4
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	()
3. TOPSOIL	(X)	()	()	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	(X)	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	(X)	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	(X)	()	()	()
12. BACKFILLING AND GRADING	(X)	()	()	()
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	(X)	()	()	(X)

INSPECTION REPORT COMMENTS
(continuation sheet)

Page 2 of 2

PERMIT NO. ACT/007/034 INSPECTION DATE November 14, 1990

(Comments are Numbered to Correspond with Topics Listed Above)

3. TOPSOIL:

The site was historically disturbed. No topsoil material was salvaged at the time of disturbance. In-situ soil material will be utilized as a substitute topsoil.

4. HYDROLOGIC BALANCE:

d. Other Sediment Control Measures:

The silt fences on the property were all performing as design. Repair work of one silt fence will be needed shortly due to weathering of the upper part of the fence. This silt fence is performing as required currently.

18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS:

One tank has been set on the property near the conveyor belt. The tank in the near future will contain an anti-freezing agent for coal. It has been reported that a second tank may be needed. Next inspection a check of surface map facilities showing tank location may be necessary.

Copy of report:

Mailed to: John Pappas (SCCC)
Mailed to SLC for: Brian Smith (OSM) Daron Haddock (DOGM)
Filed to: PFO

Inspectors Signature and Number: Stephen Demczak #39 Date: 12/3/90

