

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/034

DATE OF INSPECTION: 4/15/98

(Comments are Numbered to Correspond with Topics Listed Above)

4a. DIVERSIONS -

The diversions were spot-checked and no breaching of the ditches were noticed. During the inspection no water was flowing within the ditches.

4b. SEDIMENT PONDS -

The sediment pond did contain a small amount of water. It is highly unlikely that this sediment pond will discharge in the near future.

No hazardous conditions were noticed during the inspection.


4c. OTHER SEDIMENT CONTROL MEASURES -

The silt fences around the bend in the main haul road needs maintenance. They are presently filling up with sediment. This is a maintenance situation but could be a violation if additional storm events deposit sediment.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Dave Spillman (Soldier Canyon) Henry Austin (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: April 15, 1998

Inspector's Signature:  #39
Stephen J. Demczak