

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		Clear Water Pond	
Permit Number	ACT/007/035	Report Date	7/25/05
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	Clear Water Pond	
	Impoundment Number	004	
	UPDES Permit Number	UT 024759	
	MSHA ID Number	N/A	
IMPOUNDMENT INSPECTION			
Inspection Date	June 22, 2005		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Second Quarter Inspection 2005	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
<p>Required for an impoundment which functions as a SEDIMENTATION POND.</p>	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 4.9 acre-feet Maximum Sediment Depth Elevation = 6527 Existing Sediment Elevation = 6523+-</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>Spillway Elevation = 6530.1</p>		

file in:

Confidential

Shelf

Expandable

Refer to Record No 0023 Date 07/27/05
In C/ 0070035 St. Clair
For additional information

4. Field Information. Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on outslopes of embankments, etc.

No discharge, inlet/outlet conditions are good

No structural or hazardous conditions exist.

5. Field Evaluation. Describe any changes in the geometry of the impounding structure, average and maximum depths and elevations of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period.

Pond was essentially empty.

No structure or stability problems observed.

In accordance with the approved plan to construct the Excess Spoil Disposal area #2, the Slurry Ponds #1 and #2 no longer receive storm runoff. These storm flows are now routed either directly to the East Slurry Cell or to the Clear Water Pond. With the reclamation activities at Sunnyside Coal, both of these ponds have ample capacity to handle the storm flows without the Slurry Ponds in series.

Qualification Statement

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Signature: 

Date: 7/25/05

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT	Clear Water Pond	
---	------------------	--

CERTIFIED REPORT

IMPOUNDMENT EVALUATION (If NO, explain under Comments)	YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?	yes	
2. Is impoundment free of instability, structural weakness, or any other hazardous condition?	yes	
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	yes	

COMMENTS AND OTHER INFORMATION

None


Certification Statement:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson Senior Project Manager
 (Full Name and Title)

Signature: *S. Scott Carlson*

P.E. Number & State: 187727 UT



IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		Railcut Pond	
Permit Number	ACT/007/035	Report Date	7/25/05
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	Railcut Sediment Pond	
	Impoundment Number	007	
	UPDES Permit Number	UT 024759	
	MSHA ID Number	N/A	
IMPOUNDMENT INSPECTION			
Inspection Date	June 22, 2005		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Second Quarter Inspection 2005	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
<p>Required for an impoundment which functions as a SEDIMENTATION POND.</p>	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 4.8 acre-feet Maximum Sediment Depth Elevation = 6209 Estimated Existing Sediment Elevation = 6207+-</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>Spillway Elevation = 6212.34 Primary Drain Elevation = 6209.07 Maximum Sediment Depth Elevation = 6209.07</p>		

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT

Railcut Pond

4. Field Information. Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on outslopes of embankments, etc.

No discharge, inlet/outlet conditions are good,
no structural or hazardous conditions exist.

5. Field Evaluation. Describe any changes in the geometry of the impounding structure, average and maximum depths and elevations of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period.

No changes. Pond was essentially empty.
No structure or stability problems observed.

Qualification Statement

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Signature:



Date:

7/25/05

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT	Railcut Pond	
--	--------------	--

CERTIFIED REPORT


IMPOUNDMENT EVALUATION (If NO, explain under Comments)	YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?	yes	
2. Is impoundment free of instability, structural weakness, or any other hazardous condition?	yes	
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	yes	

COMMENTS AND OTHER INFORMATION

Certification Statement:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, P.E. Senior Project Manager
 Signature: *S. Scott Carlson* Date: 7/25/05
 P.E. Number & State: 187727 UT



IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		OCRR Pond	
Permit Number	ACT/007/035	Report Date	7/25/05
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	Old Coarse Refuse Road Sediment Pond	
	Impoundment Number	008	
	UPDES Permit Number	UT 024759	
	MSHA ID Number	N/A	
IMPOUNDMENT INSPECTION			
Inspection Date	June 22, 2005		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)	Second Quarter Inspection 2005		
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
Required for an impoundment which functions as a SEDIMENTATION POND	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 0.9 acre-feet Maximum Sediment Depth Elevation = 6394.75 Estimated Existing Sediment Elevation = 6394+-</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>Spillway Elevation = 6399.4 Primary Drain Elevation = 6395.75</p>		

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT	OCRR Pond	
---	-----------	--

CERTIFIED REPORT

IMPOUNDMENT EVALUATION (If NO, explain under Comments)	YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?	yes	
2. Is impoundment free of instability, structural weakness, or any other hazardous condition?	yes	
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	yes	

COMMENTS AND OTHER INFORMATION

None


Certification Statement:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, P.E. Senior Project Manager

Signature: *S. Scott Carlson* Date: 7/25/05

P.E. Number & State: 187727 - U



IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		Pasture Pond	
Permit Number	ACT/007/035	Report Date	7/25/05
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	Pasture Sediment Pond	
	Impoundment Number	009	
	UPDES Permit Number	UT 024759	
	MSHA ID Number	N/A	
IMPOUNDMENT INSPECTION			
Inspection Date	June 22, 2005		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Second Quarter Inspection 2005	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
Required for an impoundment which functions as a SEDIMENTATION POND	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 1.0 acre-feet Maximum Sediment Depth Elevation = 6485.5 Estimated Existing Sediment Elevation = 6484+-</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>Spillway Elevation = 6490.6 Primary Drain Elevation = 6486.6</p>		

4. Field Information. Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond had some water in the bottom.
 No discharge, inlet/outlet conditions are good,
 No structural or hazardous conditions exist.

5. Field Evaluation. Describe any changes in the geometry of the impounding structure, average and maximum depths and elevations of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period.

No changes. No structure or stability problems observed.

Qualification Statement

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Signature:  Date: 7/25/05

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT	Pasture Pond	
---	--------------	--

CERTIFIED REPORT


IMPOUNDMENT EVALUATION (If NO, explain under Comments)	YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?	yes	
2. Is impoundment free of instability, structural weakness, or any other hazardous condition?	yes	
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	yes	

COMMENTS AND OTHER INFORMATION


Certification Statement:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson - Senior Project Manager

Signature:  7/25/05

P.E. Number & State: 187727 - UT



IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		CRT Pond	
Permit Number	ACT/007/035	Report Date	7/25/05
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	New Coarse Refuse Toe Sediment Pond	
	Impoundment Number	012	
	UPDES Permit Number	UT 024759	
	MSHA ID Number	N/A	
IMPOUNDMENT INSPECTION			
Inspection Date	June 22, 2005		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Second Quarter Inspection 2005	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
Required for an impoundment which functions as a SEDIMENTATION POND	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 1.6 acre-feet Maximum Sediment Depth Elevation = 6177.0 Estimated Existing Sediment Elevation = 6176+-</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>Spillway Elevation = 6183.63 Primary Drain Elevation = 6178.2</p>		

4. Field Information. Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on out slopes of embankments, etc.

Pond was essentially empty.
 No discharge, inlet/outlet conditions are good,
 No structural or hazardous conditions exist.

5. Field Evaluation. Describe any changes in the geometry of the impounding structure, average and maximum depths and elevations of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period.

No changes. No structure or stability problems observed.

Qualification Statement

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Signature: Scott Carlson Date: 7/25/05

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT	CRT Pond	
---	----------	--

CERTIFIED REPORT

IMPOUNDMENT EVALUATION (If NO, explain under Comments)	YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?	yes	
2. Is impoundment free of instability, structural weakness, or any other hazardous condition?	yes	
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	yes	

COMMENTS AND OTHER INFORMATION


Certification Statement:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson - Senior Professional Engineer

Signature: *S. Scott*

P.E. Number & State: 187727 - UT



IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		COAL RUNOFF POND	
Permit Number	ACT/007/035	Report Date	7/25/05
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	Coal Runoff Sediment Pond	
	Impoundment Number	014	
	UPDES Permit Number	UT 024759	
	MSHA ID Number	N/A	
IMPOUNDMENT INSPECTION			
Inspection Date	June 22, 2005		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Second Quarter Inspection 2005	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
Required for an impoundment which functions as a SEDIMENTATION POND	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 1.5 acre feet Maximum Sediment Depth Elevation = 6476.0 Estimated Existing Sediment Elevation = 6475±</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>Spillway Elevation = 6477.9 Emergency Spillway Elevation = 6479.0</p>		

4. Field Information. Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on outslopes of embankments, etc.

Pond was essentially empty.
 No discharge, inlet and outlet conditions are good.
 No structural or hazardous conditions exist.


5. Field Evaluation. Describe any changes in the geometry of the impounding structure, average and maximum depths and elevations of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period.

No changes.
 No structure or stability problems observed.

Qualification Statement

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Signature:



Date:

7/25/05

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT	COAL RUNOFF POND	
---	------------------	--

CERTIFIED REPORT

IMPOUNDMENT EVALUATION (If NO, explain under Comments)	YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?	yes	
2. Is impoundment free of instability, structural weakness, or any other hazardous condition?	yes	
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	yes	

COMMENTS AND OTHER INFORMATION

None


Certification Statement:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson - Senior Project Manager
 (Full Name and Title)

Signature: *S. Scott Carlson* Date: 7/25/05

P.E. Number & State: 187727 - UT



IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		Borrow Area Pond	
Permit Number	ACT/007/035	Report Date 7/25/05	
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	Borrow Area Pond	
	Impoundment Number	016	
	UPDES Permit Number	UT 024759	
	MSHA ID Number	N/A	
IMPOUNDMENT INSPECTION			
Inspection Date	June 22, 2005		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Second Quarter Inspection 2005	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
Required for an impoundment which functions as a SEDIMENTATION POND	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 8.3 acre-feet Maximum Sediment Depth Elevation = 6513.3 Estimated Existing Sediment Elevation = 6511+-</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>Spillway Elevation = 6517.03 Primary Drain Elevation = 6514.3</p>		

4. Field Information. Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on outslopes of embankments, etc.

Pond was essentially empty.
 No discharge, inlet/outlet conditions are good,
 No structural or hazardous conditions exist.

5. Field Evaluation. Describe any changes in the geometry of the impounding structure, average and maximum depths and elevations of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period.

No changes.
 No structure or stability problems observed.

Qualification Statement

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Signature:  Date: 7/25/05

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT	Borrow Area Pond	
---	------------------	--

CERTIFIED REPORT

IMPOUNDMENT EVALUATION (If NO, explain under Comments)	YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?	yes	
2. Is impoundment free of instability, structural weakness, or any other hazardous condition?	yes	
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	yes	

COMMENTS AND OTHER INFORMATION

none

Certification Statement:

I hereby certify that: I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson, P.E. General Project Manager

Signature: *S. Scott Carlson* Date: 7/25/05

P.E. Number & State: 18772 Uta



IMPOUNDMENT INSPECTION AND CERTIFIED REPORT		East Slurry Cell	
Permit Number	ACT/007/035	Report Date 7/25/05	
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Impoundment Identification	Impoundment Name	East Slurry Cell	
	Impoundment Number	N/A	
	UPDES Permit Number	N/A	
	MSHA ID Number	1211-UT-09-02093-02	
IMPOUNDMENT INSPECTION			
Inspection Date	June 22, 2005		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Second Quarter Inspection 2005	
<p>1. Describe any appearance of any instability, structural weakness, or any other hazardous condition.</p> <p>NONE</p>			
Required for an impoundment which functions as a SEDIMENTATION POND	<p>2. Sediment storage capacity, including elevation of 60% and 100% sediment storage volumes, and, estimated average elevation of existing sediment.</p> <p>Storage Capacity = 27+- acre-feet Maximum Sediment Depth Elevation = N/A Estimated Existing Sediment Elevation = N/A</p>		
	<p>3. Principle and emergency spillway elevations.</p> <p>N/A</p>		

4. Field Information. Provide current water elevation, whether pond is discharging, type and number of samples taken, monitoring/instrumentation information, inlet/outlet conditions, or other related activities associated with the pond including but not limited to sediment cleanout, pond decanting, embankment erosion/repairs, monitoring information, vegetation on outslopes of embankments, etc.

Pond was essentially empty.
 No structural or hazardous conditions exist.

5. Field Evaluation. Describe any changes in the geometry of the impounding structure, average and maximum depths and elevations of impounded water, estimated sediment or slurry volume and remaining storage capacity, estimated volume of water impounded, and any other aspect of the impounding structure affecting its stability or function which has occurred during the reporting period.

Slurry Cell is not receiving slurry from any source, currently functioning as a sediment pond and coal fine storage. No structural or stability problems observed.

In accordance with the approved plan to construct the Excess Spoil Disposal area #2, the Slurry Ponds #1 and #2 no longer receive storm runoff. These storm flows are now routed either directly to the East Slurry Cell or to the Clear Water Pond. With the reclamation activities at Sunnyside Coal, both of these ponds have ample capacity to handle the storm flows without the Slurry Ponds in series.

Qualification Statement

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized under the direction of a Registered Professional Engineer to inspect the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

Signature: Scott Carlson Date: 7/25/05

IMPOUNDMENT INSPECTION AND CERTIFIED REPORT	East Slurry Cell	
---	------------------	--

CERTIFIED REPORT

IMPOUNDMENT EVALUATION (If NO, explain under Comments)	YES	NO
1. Is impoundment designed and constructed in accordance with the approved plan?	yes	
2. Is impoundment free of instability, structural weakness, or any other hazardous condition?	yes	
3. Has the impoundment met all applicable performance standards and effluent limitations from the previous date of inspection?	yes	

COMMENTS AND OTHER INFORMATION

Certification Statement:

I hereby certify that; I am experienced in the construction of impoundments; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of impoundments in accordance with the certified and approved designs for this structure; that the impoundment has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself or under my direction and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability in accordance with the Utah R645 Coal Mining Rules.

By: S. Scott Carlson - Senior Project Manager
 (Full Name and Title) # 187727

Signature: *S. Scott Carlson* Date: 7/25/05

P.E. Number & State: 187727 - UT



INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE		Coarse Refuse Pile
Permit Number	ACT/007/035	Report Date 7/25/05
Mine Name	SUNNYSIDE REFUSE AND SLURRY	
Company Name	SUNNYSIDE COGENERATION ASSOCIATES	
Excess Spoil Pile or Refuse Pile Identification	Pile Name:	Coarse Refuse Pile
	Pile Number	N/A
	MSHA ID Number	1211-UT-09-02093-01
Inspection Date	June 22, 2005	
Inspected By	Scott Carlson	
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)	Second Quarter Inspection 2005	
	Attachments to Report? <input type="checkbox"/> No <input checked="" type="checkbox"/> Yes	
Field Evaluation		
1.	Foundation preparation, including the removal of all organic material and topsoil.	
	N/A	
2.	Placement of underdrains and protective filter systems.	
	N/A	
3.	Installation of final surface drainage systems.	
	N/A	
4.	Placement and compaction of fill materials.	
	N/A	
	Removal of Coarse and fine Refuse Material Only	

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions.

No smokers visible

7. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

Waste Coal Removal


Certification Statement

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson - Senior Project Manager
(Full Name and Title)

Signature: *S. Scott*

P.E. Number & State: 187727 - UT



Date: 7/25/05



SCA Sunnyside

Coarse Refuse Pile – Looking West

June 22, 2005

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE		Excess Spoil Pile #1	
Permit Number	ACT/007/035	Report Date 7/25/05	
Mine Name	SUNNYSIDE REFUSE AND SLURRY		
Company Name	SUNNYSIDE COGENERATION ASSOCIATES		
Excess Spoil Pile or Refuse Pile Identification	Pile Name:	Excess Spoil Disposal Area #1	
	Pile Number	N/A	
	MSHA ID Number	1211-UT-09-02093-04	
Inspection Date	June 22, 2005		
Inspected By	Scott Carlson		
Reason for Inspection (Annual, Quarterly or Other Periodic Inspection, Critical Installation, or Completion of Construction)		Second Quarter Inspection 2005	
		Attachments to Report? <input checked="" type="checkbox"/> No <input type="checkbox"/> Yes	
Field Evaluation			
1. Foundation preparation, including the removal of all organic material and topsoil. N/A			
2. Placement of underdrains and protective filter systems. N/A			
3. Installation of final surface drainage systems. N/A			
4. Placement and compaction of fill materials. Did not receive spoils material during this Quarter.			

INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE	Excess Spoil Pile #1	
--	----------------------	--

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions.

None

7. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

No Construction occurred during this quarter. Construction in previous quarters had been proceeding in shallow lifts in general conformance with the approved plan.

No evidence exists of fires in the pile.

Certification Statement


I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson Senior Project Manager
(Full Name and Title)

Signature: *S. Scott Carlson*

P.E. Number & State: 187727 UT

7/25/05



INSPECTION AND CERTIFIED REPORT ON EXCESS SPOIL PILE OR REFUSE PILE	Excess Spoil Pile #2	
--	----------------------	--

5. Final grading and revegetation of fill.

N/A

6. Appearances of instability, structural weakness, and other hazardous conditions.

None

7. Other Comments. Describe any changes in the geometry of the Excess Spoil/Refuse Pile structure, instrumentation, average and maximum lifts of materials placed in the pile, elevations of active benches, total and remaining storage capacity of the structure, evidence of fires in the pile and abatement of such fires, volumes of materials placed in the structure during the year, and any other aspect of the structure affecting its stability or function which has occurred during the reporting period.

Both Slurry Pond #1 and Slurry Pond #2 were approved for and have been filled with coal mine waste and excess spoil in connection with construction of the Excess Spoil Disposal Area # 2. A pile is being constructed on top of the filled ponds with gentle slopes in accordance with the currently approved plan. See attached photos.

The Clearwater Pond is also part of this disposal area but will continue to function as a sediment pond until such time as it is needed as a disposal site.

In accordance with the approved plan, SCA has begun removing the coal fines lining the old slurry ditch along the east side of this pile. These materials are being used in the power plant. Removal of these materials facilitates the construction of the east access road and drainage ditch shown on the approved plan. See attached photos.


Certification Statement

I hereby certify that; I am experienced in the construction of earth and rock fills; I am qualified and authorized in the State of Utah to inspect and certify the condition and appearance of earth and rock fills in accordance with the certified and approved designs for this structure; that the fill structure has been maintained in accordance with approved design and meet or exceed the minimum design requirements under all applicable federal, state and local regulations; and, that inspections and inspection reports are made by myself and include any appearances of instability, structural weakness or other hazardous conditions of the structure affecting stability.

By: S. Scott Carlson Senior Project Manager
(Full Name and Title)

Signature: *S. Scott Carlson*

P.E. Number & State: 187727 - UT





Excess Spoil Disposal Area #2 looking south

June 22, 2005



Exposed Wall along east side of Excess Spoil Disposal Area #2

June 22, 2005