



State of Utah

DEPARTMENT OF NATURAL RESOURCES

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas and Mining

JOHN R. BAZA
Division Director

November 12, 2015

Gerald Hascall, Plant Manager
Sunnyside Cogeneration Associates
One Power Plant Road
P.O. Box 159
Sunnyside, Utah 84539

Subject: Midterm Completion Response, Sunnyside Cogeneration Associates, Sunnyside Refuse, C/007/0035, Task ID #4983

Dear Mr. Hascall:

The Division has reviewed your application. The Division has identified deficiencies that must be addressed before final approval can be granted. The deficiencies are listed as an attachment to this letter.

The deficiencies authors are identified so that your staff can communicate directly with that individual should questions arise. The plans as submitted are denied. Please resubmit the entire application by no later than December 11, 2015.

If you have any questions, please call me at (801) 538-5325.

Sincerely,

Daron R. Haddock
Coal Program Manager

DRH/sqs
O:\007035.SRS\WG4983 MIDTERM RESPONSE\Deficiencies.doc



GARY R. HERBERT
Governor
GREG BELL
Lieutenant Governor

State of Utah
DEPARTMENT OF NATURAL RESOURCES
MICHAEL R. STYLER
Executive Director
Division of Oil, Gas and Mining
JOHN R. BAZA
Division Director

Technical Analysis and Findings

Utah Coal Regulatory Program

PID: C0070035
TaskID: 4983
Mine Name: SUNNYSIDE REFUSE & SLURRY
Title: MIDTERM COMPLETION RESPONSE

Operation Plan

Topsoil and Subsoil

Deficiencies Details:

R645-301-121.100, The revised information does not meet the requirements of R645-301-230, Operation Plan, because topsoil piles (Clear water pond, Hoist house, and Slurry Pond topsoil piles) which are no longer existant are still shown on Drawings 2-1 and 5-1. In addition, Plate 8-4 reduces dedicated topsoil replacement volumes because of the use of the aforementioned topsoil stockpiles, but does not reduce the area to receive the topsoil which is inconsistent with the narrative.

pburton