



**INSPECTION REPORT**  
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/038

DATE OF INSPECTION: 11/15/94

(Comments are Numbered to Correspond with Topics Listed Above)

4a. DIVERSIONS -

Diversions were spot-checked with one ditch, located 75 feet past the main gate to Willow Creek needing maintenance. A road was installed for equipment access to the drill site. Building the new road caused some sediment deposit in the ditch.

4c. OTHER SEDIMENT CONTROL MEASURES -

Silt fences have been installed where equipment crossed the Willow Creek for opening rock tunnels this past summer. This past month equipment was again used to perform drilling, using this crossing. The silt fences were not re-installed after using the crossing. Thus, a notice of violation was issued (94-39-6-1). The silt fencing material was lying on the ground.

**Note:** This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:

Mailed to: Cyprus Western Coal Company

Bernie Freeman (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: November 28, 1994

Inspector's Signature:  #39  
Stephen J. Demczak