

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/038

DATE OF INSPECTION: September 7, 1994

(Comments are Numbered to Correspond with Topics Listed Above)

1. Permit -

The segments of the exploration site could be reclaimed if the permit holder does not need this site for development of the future coal mine. If these sites are not required the operator should submit a reclamation schedule. If sites are still required the operator should submit a letter describing the possible activities still required for these sites.

3. Topsoil -

The topsoil piles showed no wind or water erosion. These do have a small amount of vegetative cover.

4a. Diversions -

The diversions were spot-checked with no apparent breaching occurring. The diversions were dry.

4b. Other Sediment Control Measures -

Silt fences were functioning as designed with no bypassing or overtopping occurring. There were a few small rain storms in the month of August.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Copy of this Report:

Mailed to: Cyprus Western Coal Company Bernie Freeman (OSM)
Given to: Joe Helfrich (DOGM) Filed to: Price Field Office
Date: September 19, 1994

Inspector's Signature and Number:  #39
Stephen J. Demczak