

INSPECTION REPORT
(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/007/038

DATE OF INSPECTION: 7-10-95

(Comments are Numbered to Correspond with Topics Listed Above)

4A. DIVERSIONS -

The diversions were spot-checked and were performing as designed. There were no signs of breaching or major sediment build-up.

4C. OTHER SEDIMENT CONTROL MEASURES -

The silt fences throughout the property were checked. Maintenance is needed at the first rock tunnel located at Willow Creek. Operator will repair the silt fence. No sediment left the disturb area.

The operator will rip the drill pad ground which was used this summer. This will be the alternate sediment control measure for this area. Also, the operator will seed the area this fall.

7. COAL MINE WASTE -

The drill pad area used this summer has wood debris which the operator will remove. This material came from the public and the prior pre-law coal mine.

13. REVEGETATION -

The drill holes located on the AML coal mine waste pile was seeded last year. The vegetation that covers this area was hard to distinguish from the AML reclamation of this area. The main reason for the vegetative growth is the large quantity of rainfall this year.

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas, and Mining.

Copy of this Report:


Mailed to: Cyprus Western Coal Company

Donna Griffin (OSM)

Given to: Joe Helfrich (DOGM)

Filed to: Price Field Office

Date: July 14, 1995

Inspector's Signature:  #39
Stephen J. Demczak