

0013

COAL SYSTEMS, Inc.
CONSULTANTS/ENGINEERS

#7

L. G. MANWARING, P.E.
President

P.O. BOX 17117
SALT LAKE CITY, UTAH 84117

Area Code 801
261-4500

July 1, 1986

RECEIVED
JUL 02 1986

Mr. John J. Whitehead
Permit Supervisor
DIVISION OF OIL, GAS, AND MINING
3 Triad Center, Suite 350
Salt Lake City, Ut. 84180-1203

**DIVISION OF
OIL, GAS & MINING**

Re: J. B. King Mine Post Monitoring
June Inspection

Dear Mr. Whitehead:

A post-monitoring inspection of the reclaimed J. B. King Mine Site was conducted June 26 in accord with permit requirements.

Due to the fact that little moisture has been received at the mine site, the surface remains much the same as when reclaimed in the fall of 1985. No significant erosion of slopes, ditches, etc. has occurred and thus no repairs are required.

Lack of precipitation continues to hamper growth of the fall seed and spring seedlings plantings. Moisture level in the soil is approximately 6 inches below the surface.

A levels survey was conducted on the subsided area. The report of the survey will be prepared within the next week. A visual inspection of the subsided area shows no new peripheral cracks which indicates a currently stable condition.

Sincerely,

COAL SYSTEMS, Inc.,

L. G. Manwaring
L. G. Manwaring, P.E.
President

LGM/bm

cc: Mr. M. H. O'Donnell, Western States Minerals Corporation

