

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/002

DATE OF INSPECTION: 8/31/95

(Comments are Numbered to Correspond with Topics Listed Above)

The operator had installed a weather station on site.

4. HYDROLOGIC BALANCE:

- a. Diversions - Evidence of discontinuous flows were observed in the recently reconstructed channel. To date the reconstructed channels have had water flows.
- b. Sediment Ponds and Impoundments - The sediment pond was dry.

13. REVEGETATION

The site was very dry. Cool season grasses were dormant.

Copy of this Report:

Mailed to: OSM, E.M. Gerick (WSMC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature:

Susan M. White #35 Date: 9/6/95