

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/002

DATE OF INSPECTION: 1/18/96

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

Evidence of less than 1 inch of snow remained in shaded areas.

13. REVEGETATION

Cows were observed on the range in the general area of the mine, but not on the mine site. No elk or large ungulates had used the revegetated area.

14. SUBSIDENCE

Walked the area of previous subsidence with no observations of new cracks reforming. Burrowing animals are using the filled cracked areas. A vehicle had recently driven around the perimeter of the subsided area.

Copy of this Report:

Mailed to: OSM, E.M. Gerick (WSMC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature:

Susan M. White

#35 Date: 1/19/95