

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/002

DATE OF INSPECTION: 7/22/97

(Comments are Numbered to Correspond with Topics Listed Above)

4. HYDROLOGIC BALANCE:

The sediment pond was dry. Mr. Gerrick committed to getting in the new pond outlet design within a few weeks. The consultant, Hansen, Allen, and Luce, working on the design has contacted the Division to review the design.

13. REVEGETATION

The site appeared very dry and most new growth was in a dormant condition.

The soil cryptobiotic test plots were examined. Several of the sugar treated plots appeared to have a black microphytic crust developing on the surface. Mr. Davidson was going to look into testing. A visual observation indicated that all sugar treated plots contained almost no weeds.

Copy of this Report:

Mailed to: OSM, E.M. Gerick (WSMC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: *Susan White* #35 Date: 7/31/97