



## INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/002

DATE OF INSPECTION: 5/15/97

(Comments are Numbered to Correspond with Topics Listed Above)

### 4. HYDROLOGIC BALANCE:

The sediment pond was dry.

### 13. REVEGETATION

The site appeared very dry, however, new growth was apparent on all plants. Some recent germination was observed. In general the vegetation on site looked good compared to other times of the year. Globemallow, an herbaceous species, was present on the recently reseeded areas. Recruitment from greasewood was noted. Greasewood, although a native, can be undesirable if large amounts are present. At this time it is not a problem. As expected, numerous weedy species were observed on the recently disturbed area.

### 14. SUBSIDENCE

The area of previous subsidence was observed. The operator had recently dumped sand in piles over the cracks. The sand appeared to have been borrowed from a road cut near by. The undisturbed vegetation was driven on to dump the sand. The operator was asked not to fill the cracks again unless they present a public hazard.

Copy of this Report:

Mailed to: OSM, E.M. Gerick (WSMC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature:

Susan M. White

#35 Date:

6/5/97