

0010

### Document Information Form

Mine Number: C/015/004

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: August 6, 1981

Explanation:

Inspection Memo

\_\_\_\_\_

cc:

File in: C/015, 004, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date \_\_\_\_\_ For additional information

August 6, 1981

Inspection Memo  
to Coal File:

RE: Beaver Creek Coal Co.  
Huntington #4  
ACT/015/004  
Emery County, Utah

DATE: June 12, 1981  
TIME: 1:00 p.m.  
WEATHER: Clear and Warm  
COMPANY OFFICIAL: Dan Guy  
STATE OFFICIALS: Tom Portle and Jead Doutré

Compliance with Permanent Performance Standards

771 et al Permits

Applicable permits were available at the Price office. Operations being conducted according to permit area modification.

USGS #U-33454 was approved February 16, 1977.

State mining permit--ACT/015/004 issued August 25, 1977.

OSM mine plan was approved, #UT0004, January 30, 1980.

817.11 Signs and Markers

The mine identification sign was visible and complete in detail. Mr. Guy was made aware of the need for perimeter markers around the disturbed area. Buffer zone markers were in place.

817.21-.25 Topsoil

The topsoil pile is located as per plan. A violation, No. 2 of 3, 81-3-3 had been issued because of water erosion to the stockpile. A ditch and berm had to be extended to cover the entire bottom of the stockpile. This had been accomplished and the NOV (No. 2 of 3) was terminated at this sitme. NOTE: May 14, 1981, memo extending this NOV abatement period.

817.41-57 Hydrologic Balance

The sediment ponds are sound, without no sign of tension cracks.

The NPDES permit #0023116 was issued by EPA November 11, 1977. Any discharge from the sediment ponds would find its way into Huntington Canyon. This has not happened.

Stream buffer zones are at the entrance to the minesite and along the Forest Service road.

File in:

- Confidential
- Shelf
- Expandable

Refer to Record No 0010 Date 8-6-81

In C/ 015, 004, Internal

For additional information

817.89 Noncoal Waste Disposal


A violation, No. 3 of 3 in group 81-3-3-3, was abated on May 14, 1981. This is an on-going problem.

817.121-.126 Subsidence Control

Beaver Creek Coal Company has a Subsidence Control and Monitoring plan, established under a cooperative agreement with Manti-LaSal National Forest of the U. S. Department of the Interior August 27, 1979. Using color aerial photography. Monuments will be flagged each year prior to flight. There are no buildings on the mountain to be effected, except those of the mining company.

817.150-.176 Roads

The access road to the second level is a Class I haulage road to the coal pile.

  
JEAN L DOURE  
RECLAMATION OFFICER

cc: Tom Ehmett, OSM  
Dan Guy, Beaver Creek  
Inspection Staff

JLD/btm

Statistics:

See Soldier Creek memo dated June 11, 1981.  
Grant: A & E