

0001

Document Information Form

Mine Number: C/015/007

File Name: Internal

To: DOGM

From:

Person N/A

Company N/A

Date Sent: December 13, 1983

Explanation:

Inspection Memo

cc:

File in:
C/015, 0004, Internal

Refer to:

- Confidential
- Shelf
- Expandable

Date _____ For additional information

December 13, 1983

Inspection Memo
to Coal File:

RE: Huntington Canyon #4 Mine
Beaver Creek Coal Company
ACT 015/004, Folder #7
Emery County, Utah

DATE: November 17, 1983

TIME: 10 a.m. - 1 p.m.

WEATHER: Clear

COMPANY OFFICIAL: Dan Guy

STATE OFFICIAL: Barton Kale

ENFORCEMENT ACTION: None

Compliance With Permanent Performance Sandards

UMC 771 et al Permits

Interim program approval was granted by OSM on January 30, 1980. The State mining approval dated August 25, 1977 was granted under the Mined Land Reclamation Act. Final approval is targeted for December 1983.

A letter dated March 22, 1982 from the Department of Health states air quality approval for Huntington Canyon No. 4 mine production increase.

There is a special use permit dated November 19, 1981 from the Forest Service to operate stream flow water monitoring and subsidence equipment.

UMC 817.11 Signs & Markers

The entrance sign is posted as required and perimeter markers were observed throughout the mine site.

UMC 817.21-25 Topsoil

There were no topsoil problems at this time.

File in:

Confidential

Shelf

Expandable

Refer to Record No. 0001 Date 12-13-83

In C/ 015, 005, Internal

For additional information

Inspection Memo to Coal File:
ACT 015/004, Folder #7
December 13, 1983
Page 2

UMC 817.41-.57 Hydrologic Balance

Disturbed area diversion from the upper pad to the coal stockpile pad is being remodeled. The culvert is going to be dropped closer to pad level for stability and covered with fill to protect it from coal coming out the chute.

The sediment pond was being cleaned while the inspector was on site. The waste was being loaded on to trucks and taken to the preparation plant. The access road was somewhat disturbed when the dragline was taken down to the pond embankment. This road should be bermed and stabilized where needed upon completion of the pond cleaning.

UMC 817.52 Hydrologic Balance: Water Monitoring

The NPDES permit No. UT-0023116 was available upon request. The receiving water is Mill Creek tributary to Huntington Creek.

There were no water quantity problems at this time. The latest water data on hand was sampled September 30, 1983 and received during the month of October.

UMC 817.89 Disposal of Non-Coal Waste

Trash and waste bins were in place and waste material was segregated to separate scrap metal and trash. The non-coal waste was well contained.

UMC 817.133 Subsidence Control

See October 25, 1983 for description of subsidence monitoring plan.


BARTON KALE
FIELD SPECIALIST

BK/re

cc: Tom Ehmett, OSM
Dan Guy, BCCC
Joe Helfrich, DOGM
Steve Cox, DOGM

Statistics: See Kaiser Steel Memo dated November 28, 1983