



File

gn
 015/00445

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: Nov. 24, 1987
1:00 p.m. to 4:00 p.m.

Permittee and/or Operators Name: Beaver Creek Coal Co.
 Business Address: P.O. Box 1378 Price, Utah 84501
 Mine Name: Huntington Canyon #4 Permit Number: ACT/015/004
 Type of Mining Activity: Underground Surface Other
 County: Emery
 Company Official (s): Dan Guy
 State Official(s): Bill Malencik
 Partial: Complete: Date of Last Inspection: Oct. 28, 1987
 Weather Conditions: Clear, cool, site dry
 Acreage: Permitted 2600 Disturbed 12.5 Regraded 12 Seeded 12 Bonded 12.5
 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. PERMITS	(X)	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	()	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	()	(X)	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	(X)	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	()	()	(X)	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	(X)	()	()
10. SLIDES AND OTHER DAMAGE	()	()	(X)	()
11. CONTEMPORANEOUS RECLAMATION	()	()	(X)	()
12. BACKFILLING AND GRADING	()	()	(X)	()
13. REVEGETATION	(X)	()	()	()
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	()
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	(X)	()



355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/004

DATE OF INSPECTION Nov. 24, 1987

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENT:

The general area had received snow. The road at the upper end was snow covered, including the north slopes across from the rehabed mine site. Since most of the mine site is on a southerly exposure, most of the area, including the upper bench, was not snow covered.

2. SIGNS AND MARKERS:

Required signs were observed at each primary access point. Perimeter markers are the same as noted in the inspection report of October 28, 1987. However, Dan Guy stated that he has discussed the matter of perimeter markers with John Whitehead, DOGM. He is awaiting word from Whitehead before he will take any further action on this matter. A copy of this inspection is being sent to Whitehead for any followup action as appropriate.

4c. SEDIMENT PONDS:

The sediment pond contained a small amount of water. It covered about 2/3 of the sediment pond bottom and was frozen. No problems were noted with the pond.

4d. OTHER SEDIMENT CONTROL MEASURES:

The rill erosion on the lower pad noted in the previous inspection report had been corrected even though they were only 5 inches deep. The six rills were riprapped and/or protected by shovel work. No other similar rills were observed.

Copy of this Report:

Mailed to: Dan Guy, Beaver Creek Coal

Mailed to: SLC-DOGM for Brian Smith, OSM; Joe Helfrich and John Whitehead, DOGM

Inspectors Signature and Number: Bill Malencik #26 Date: Nov. 25, 1987