



## INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/004

DATE OF INSPECTION: 8/19/95

(Comments are Numbered to Correspond with Topics Listed Above)

Several elk hunters were in the area, so the upper road was not walked due to safety concerns.

### 2. SIGNS AND MARKERS

Several of the disturbed area markers could not be located around the lower area, the operator was asked to remark the area.

### 4. HYDROLOGIC BALANCE:

No flows were observed through the reclaimed sediment pond area.

The drainage near the old topsoil pile had not been armored as discussed with Sharon Falvey, Division Hydrologist, and Mr. Guy in August. Mr. Guy stated that he still intended to do the work.

### 13. REVEGETATION

Mr. Guy stated that he had request that the SCS look at the reference areas and provided a range condition classification.

Copy of this Report:

Mailed to: OSM, Paige Beville(MCC)

Given to: Joe Helfrich (DOGM)

Inspector's Signature: *Susan M. White* #35 Date: 10/17/95