



0007

STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

RECEIVED  
JUN 27 1988

*jm*

Norman H. Bangerter, Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, Utah 84118 • 801-538-5340

DIVISION OF  
OIL, GAS & MINING  
INSPECTION REPORT

INSPECTION DATE & TIME: March 8, 1988  
2:00 p.m. to 5:00 p.m.

Permittee and/or Operators Name: California Portland Cement  
Business Address: 695 South Rancho Avenue Colton, CA 92324-0514  
Mine Name: Hidden Valley Permit Number: INA/015/007  
Type of Mining Activity: Underground  Surface  Other   
County: Emery State Utah  
Company Official (s): None  
State Official(s): Harold G. Sandbeck and Brent Stettler  
Partial:  Complete:  Date of Last Inspection: Feb. 12, 1988  
Weather Conditions: Cold and windy  
Acreage: Permitted 960 Disturbed 7 Regraded 7 Seeded 7 Bonded 7  
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( X )	( )	( )	( X )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( X )	( )	( )	( X )
b. DIVERSIONS	( )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( X )	( )	( )	( X )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: INA/015/007

DATE OF INSPECTION March 8, 1988

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

Ground conditions were semi-frozen with no snow cover on the site. No significant erosion problems were observed.

2 SIGNS AND MARKERS:

As noted in the February 12, 1988, inspection report, the main entrance sign at the end of the blacktop road was down. The sign has been erected and all appears in order.

4a. STREAM CHANNEL DIVERSIONS:

The stream channel was inspected and it appears to be stable with no problems observed.

4d. OTHER SEDIMENT CONTROL MEASURES:

The silt fences were inspected and no stability problems were noted. As noted in previous inspection reports, some silt fences had been repaired by increasing the fence height. This increase in height may cause stability problems later.

Copy of this Report:

Mailed to: John Rains, CPC

Mailed to SLC for: Brian Smith, DSM; Joe Helfrich, DOGM

Filed to: PFO

Inspectors Signature and Number: Harold G. Sandbeck #27 Date: Mar. 9, 1988