

3-31-89
7085

0012



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

John RUS

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: March 7, 1989
9:30 a.m. - 11:30 a.m.

Permittee and/or Operators Name: California Portland Cement
Business Address: 695 South Rancho Avenue Colton, CA 92324-0514
Mine Name: Hidden Valley Permit Number: INA/015/007
Type of Mining Activity: Underground Surface Other
County: Emery State: Utah
Company Official(s): None
State Official(s): Bill Warmack
Partial: Complete: Date of Last Inspection: February 1, 1989
Weather Conditions: Overcast and cool
Acreage: Permitted 960 Disturbed 7 Regraded 7 Seeded 7 Bonded 7
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	<u>YES</u>	<u>NO</u>	<u>N/A</u>	<u>COMMENTS</u>
1. <u>PERMITS</u>	()	()	()	()
2. <u>SIGNS AND MARKERS</u>	(X)	()	()	(X)
3. <u>TOPSOIL</u>	()	()	()	()
4. <u>HYDROLOGIC BALANCE:</u>				
a. <u>STREAM CHANNEL DIVERSIONS</u>	()	()	()	()
b. <u>DIVERSIONS</u>	()	()	()	()
c. <u>SEDIMENT PONDS AND IMPOUNDMENTS</u>	()	()	()	()
d. <u>OTHER SEDIMENT CONTROL MEASURES</u>	(X)	()	()	(X)
e. <u>SURFACE AND GROUNDWATER MONITORING</u>	()	()	()	()
f. <u>EFFLUENT LIMITATIONS</u>	()	()	()	()
5. <u>EXPLOSIVES</u>	()	()	()	()
6. <u>DISPOSAL OF DEVELOPMENT WASTE AND SPOIL</u>	()	()	()	()
7. <u>COAL PROCESSING WASTE</u>	()	()	()	()
8. <u>NONCOAL WASTE</u>	()	()	()	()
9. <u>PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES</u>	()	()	()	()
10. <u>SLIDES AND OTHER DAMAGE</u>	()	()	()	()
11. <u>CONTEMPORANEOUS RECLAMATION</u>	()	()	()	()
12. <u>BACKFILLING AND GRADING</u>	()	()	()	()
13. <u>REVEGETATION</u>	()	()	()	()
14. <u>SUBSIDENCE CONTROL</u>	()	()	()	()
15. <u>CESSATION OF OPERATIONS</u>	()	()	()	()
16. <u>ROADS</u>				
a. <u>CONSTRUCTION</u>	()	()	()	()
b. <u>DRAINAGE CONTROLS</u>	()	()	()	()
c. <u>SURFACING</u>	()	()	()	()
d. <u>MAINTENANCE</u>	()	()	()	()
17. <u>OTHER TRANSPORTATION FACILITIES</u>	()	()	()	()
18. <u>SUPPORT FACILITIES</u>				
<u>UTILITY INSTALLATIONS</u>	(X)	()	()	(X)

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/007

DATE OF INSPECTION March 7, 1989

(Comments are Numbered to Correspond with Topics Listed Above)

GENERAL COMMENTS:

The mine site was free of snow, ground conditions were moist. Cattle were observed grazing on the adjacent areas. Ivie Creek was flowing and the majority of the ice was gone.

2. SIGNS AND MARKERS:

The mine I.D. sign has been reposted at a lower elevation. Stream buffer zone signs were observed and in good repair.

4d. OTHER SEDIMENT CONTROL MEASURES:

1. Repairs have been made to silt fences and berms that did not fair well with winter.
2. Rills have developed on the northern portion of the A seam and western portion of the B seam fill slopes. Measurements indicated that the areas were still in compliance with UMC 817.105 since the rills have not developed beyond 9 inches in depth (A seam: 6-8 inches, B seam: 4-6 inches). However, based upon the season and the likelihood of precipitation events, the operator should undertake preventive maintenance to ensure that these rills do not further develop. Mr. Rains (CPC) was contacted on 3/8/89 regarding the Division's concerns of additional erosion and stabilization of the area.

18. SUPPORT FACILITIES:

The fence at the main gate has been tightened and appears to be in good repair. Also, the drift fences above and below the site were observed and found to be functioning properly.

Copy of this Report:

Mailed to: John Rains, California Portland Cement; Karla Knoop (JBR)
Mailed to SLC for: Brian Smith, OSM; Joe Helfrich, DOGM
Filed to: PFO

Inspectors Signature and Number: William A. Warmack #30 Date: March 8, 1989

William A. Warmack 3/8/89