



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

Norman H. Bangertter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

Page 1 of 1

INSPECTION REPORT

INSPECTION DATE & TIME: 1200 to 1400, 10 September 1991

Permittee and/or Operator's Name: Cal Mat Company
Business Address: 1801 University Drive
Phoenix, Arizona 85034

Mine Name: Hidden Valley Permit Number: ACT/015/007
Type of Mining Activity: Underground: X Surface: Other:
County: Emery State: Utah

Company Official(s): N/A
State Officials(s): Hugh Klein, Susan White, Tom Munson (DOGM)

Federal Official(s): N/A
Partial: Complete: X Date of last Inspection: 31 July 1991

Weather Conditions: Clear to partly cloudy and mild

Acreage:
Permitted: 950 Disturbed: 7 Regraded: 7 Seeded: 7 Bonded: 7
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	()	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	(X)
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	()	()	(X)	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	(X)
e. SURFACE AND GROUNDWATER MONITORING	(X)	()	()	()
f. EFFLUENT LIMITATIONS	(X)	()	()	()
5. EXPLOSIVES	()	()	(X)	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	(X)	()
7. COAL PROCESSING WASTE	()	()	(X)	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	(X)	()	()	(X)
10. SLIDES AND OTHER DAMAGE	(X)	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	(X)	()
12. BACKFILLING AND GRADING	(X)	()	()	(X)
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	(X)	()
15. CESSATION OF OPERATIONS	()	()	(X)	()
16. ROADS				
a. CONSTRUCTION	(X)	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	(X)
c. SURFACING	(X)	()	()	()
d. MAINTENANCE	(X)	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	(X)	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	(X)	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 3

PERMIT NUMBER: ACT/015/007 DATE OF INSPECTION: 10 SEPTEMBER 1991

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments

Although the region recently experienced several periods of high intensity rainfall, the site did not appear to have received any significant moisture.

2)

The mine identification sign is clearly visible as well as legible. Disturbed area markers and stream buffer zone signs are also in place.

4a)

The stream channel diversion was observed to be without problems.

4d)

Silt fences below the A and B coal seam are functional; certain sections should be considered for maintenance or replacement in the near future. In addition, rills are becoming well formed on the west-facing slope at the end of the matted area below the A seam. There is also a rill forming in the gap between erosion mats on the slope below the B seam.

9)

Flow within the stream channel appears to be at or near the level it was observed to be in May during a partial inspection with Bill Malencik.

12)

The highwall issue has not yet been resolved. The Division and OSM are presently engaged in discussions regarding this matter.

13)

Vegetation was observed to be minimal in areas of erosion matting. The site was fairly dry with the exception of some depressions containing standing water. In a few other areas, the soil appeared damp.

INSPECTION REPORT

(Continuation sheet)

Page 3 of 3

PERMIT NUMBER: ACT/015/007 DATE OF INSPECTION: 10 SEPTEMBER 1991

(Comments are Numbered to Correspond with Topics Listed Above)

16b)

Road berms and the outslope drainage areas appear to be in good working order.


Copy of this Report:

Mailed to: Lee Edmonson (Cal Mat)

Brian Smith (OSM)

Given to: Joe Helfrich (Utah DOGM)

Utah DOGM/Price Field Office

Inspector's Signature & Number:  #40

Date: 12 September 1991