

June 24, 1987

TO: File

FROM: Pamela Grubaugh-Littig, Reclamation Engineer *pl*

RE: Mid-Term Review Deficiencies, Diamond Shamrock Company, Trail Mountain Mine, ACT/015/009, Folder #2, Emery County, Utah

1. Two complete, current and comprehensive copies of the Mining and Reclamation Plan for the Trail Mountain Mine must be submitted to the Division. This will include the merging of Tract 1 and Tract 2 into one MRP.

2. All references to Natomas Trail Mountain Coal Company must be changed to the updated applicant's name.

UMC 782.13(a)(2) The owners of record of the surface area and of coal rights must be updated, if necessary.

UMC 782.13(b)(1) The officers and directors of the applicant must be updated, if necessary.

UMC 782.13(b)(2) The principal shareholder of the applicant must be updated.

UMC 782.13(c) The owners of record of surface and subsurface areas contiguous to the permit must be updated, if necessary.

UMC 771.23(b) and 784.23(b) Figure 3-1 (received 3/22/85) must be updated to accurately reflect the on-site surface facilities as they exist today. Figure 3-5 must also be updated.

UMC 784.23(b)(1) and (b)(5) Fencing and topsoil sites should be shown on the surface facilities map. The fencing mentioned on page 3-21b must include all fencing on the property.

UMC 784.23(b)(4) The coal yard described on page 3-11 was never developed; please update the MRP to reflect this.

Page 2
Memo to File
ACT/015/009
June 24, 1987

UMC 784.11 The mining plan mentioned on page 3-11a as Figure 3-6 is missing. Please submit.

UMC 784.13(b)(2) An updated reclamation cost estimate should be submitted with this mid-term review.

UMC 817.11(c)(2) The signs portrayed on page 3-22 are not correct as shown. Please correct and update.

djh
cc: J. Whitehead
9075R/25