



# State of Utah

DEPARTMENT OF NATURAL RESOURCES  
DIVISION OF OIL, GAS AND MINING

*gch*

Norman H. Bangerter  
Governor  
Dee C. Hansen  
Executive Director  
Dianne R. Nielson, Ph.D.  
Division Director

355 West North Temple  
3 Triad Center, Suite 350  
Salt Lake City, Utah 84180-1203  
801-538-5340

## INSPECTION REPORT

INSPECTION DATE & TIME: 24 September 1992  
08:30 to 15:00

Permittee and/or Operator's Name: Mountain Coal Company  
Business Address: P.O. Box 1378 Price, Utah 84501  
Mine Name: Trail Mountain #9 Permit Number: ACT/015/009  
Type of Mining Activity: Underground X Surface    Other     
County: Emery Company Official(s): Dan Guy  
State Officials(s): Jess Kelley  
Federal Official(s): None  
Partial: X Complete:    Date of last Inspection: 27 August 1992  
Weather Conditions: Sunny and warm  
Acreage: Permitted-1450 Disturbed-9.45 Regraded-   Seeded-    
Bonded-9.45 Enforcement Action: None

### COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	(X)	( )	( )	(X)
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	( )	( )	(X)
b. DIVERSIONS	(X)	( )	( )	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	( )	( )	(X)
d. OTHER SEDIMENT CONTROL MEASURES	(X)	( )	( )	(X)
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	(X)	( )	( )	(X)
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
d. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	( )	( )	( )	( )

## INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/009 DATE OF INSPECTION: 24 September 1992

(Comments are Numbered to Correspond with Topics Listed Above)

### 2. SIGNS AND MARKERS

All 18 perimeter markers are in place and in good condition, as shown on Plate 3-1, 'Surface Facilities'. The 3 permit identification signs shown on Plate 3-1 are likewise in place and in good condition.

### 4. HYDROLOGIC BALANCE

a) **Stream Channel Diversions**--Cottonwood Creek is flowing. The main 66" CMP bypass culvert is unobstructed and its inlet and trash rack are also unobstructed and in good repair.

b) **Diversions**--The large concrete disturbed ditch which borders the east edge of the property is unobstructed and in good repair. The 3 conveyance pipes which drain the upper road are in place and unobstructed.

c) **Sediment Ponds and Impoundments**--The sediment pond contains some water, but has not discharged. The sediment pond embankments are somewhat vegetated and are free from erosion gullies and appear to be stable.

d) **Other Sediment Control Measures**--The berms around the culinary water supply system at the north end of the property and those on the upper road are in place and in good repair.

### 13. REVEGETATION

The hillside above the parking area at the north end of the property is sustaining some vegetation, but is mostly bare. The hillside above the sediment pond is covered with vegetation which is mostly dead. The topsoil stockpile adjacent to the portal is covered with vegetation and appears to be protected thereby.

Copy of this Report:

Mailed to: Bernie Freeman (OSM); Dan Guy (Mountain Coal)

Given to: Joe Helfrich (DOGM); Price Field Office (DOGM)

Inspector's Signature: Gene W. Kelley #34 Date: 9/25/92