

0010



State of Utah

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

gpg

Norman H. Bangerter
Governor
Dee C. Hansen
Executive Director
Dianne R. Nielson, Ph.D.
Division Director

355 West North Temple
3 Triad Center, Suite 350
Salt Lake City, Utah 84180-1203
801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 23 June 1992
14:00 to 18:30

Permittee and/or Operator's Name: Mountain Coal Company
Business Address: P.O. Box 1378 Price, Utah 84501
Mine Name: Trail Mountain #9 Permit Number: ACT/015/009
Type of Mining Activity: Underground X Surface Other
County: Emery Company Official(s): Dan Guy
State Officials(s): Jess Kelley
Federal Official(s): None
Partial: X Complete: Date of last Inspection: 18 May 1992
Weather Conditions: Sunny and hot
Acreage: Permitted-1415 Disturbed-9.45 Regraded- Seeded-
Bonded-9.45 Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	()	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	(X)	()	()	(X)
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	(X)
b. DIVERSIONS	(X)	()	()	(X)
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	(X)
d. OTHER SEDIMENT CONTROL MEASURES	()	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE & SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	()	()	()	()
8. NONCOAL WASTE	()	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	()	()	()	()
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	(X)	()	()	(X)
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	()	()	()	()
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT

(Continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/009 DATE OF INSPECTION: 23 June 1992

(Comments are Numbered to Correspond with Topics Listed Above)

2. SIGNS AND MARKERS

Site identification signs, disturbed area boundary markers, and stream buffer zone markers are in place and in good condition.

3. TOPSOIL

The topsoil stockpile adjacent to the portal area is in good condition. The pile is covered by a thick growth of vegetation and shows no sign of erosion damage or contamination.

4. HYDROLOGIC BALANCE

(a) Stream Channel Diversions--The large CMP stream channel diversion beneath the site is in good condition and free of debris, as is the trash rack at its entrance.

(b) Diversions--The drainage ditch along the highway is clean and in good repair. Culverts beneath site access roads are clean and in good repair.

(c) Sediment Ponds and Impoundments--The sediment pond contains some water and is in good condition. Sediment accumulation is small. Pond embankments are vegetated and show no sign of erosion.

13. REVEGETATION

In general, vegetation on the site is in good condition but rather sparse. The area above the pond was seeded and mulched in the Fall of 1991. This area now contains more vegetation than at any time in the writer's memory. This new vegetation, while small, appears to be preventing erosion in this area, despite last month's heavy rains.

Copy of this Report:

Mailed to: Dan Guy/Mountain Coal; Bernie Freeman/OSM

Given to: Joe Helfrich (DOGM); Price Field Office/DOGM

Inspector's Signature: *Gene W. Kelley* #34 Date: 6/26/92