



State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR.
Governor

GARY R. HERBERT
Lieutenant Governor

Table with 2 columns: Company, Name, Title. Row 1: Chuck Semborski, Environmental Supervisor. Row 2: OGM, Pete Hess, Environmental Scientist III.

Inspection Report

Table with 2 columns: Field, Value. Fields include Permit Number (C0150009), Inspection Type (COMPLETE), Inspection Date (Wednesday, February 15, 2006), Start Date/Time (2/15/2006 8:45:00 AM), End Date/Time (2/15/2006 10:35:00 AM), Last Inspection (Friday, October 21, 2005).

Inspector: Pete Hess, Environmental Scientist III

Weather: Clear; cold; windy. Snow forecast.

InspectionID Report Number: 868

Accepted by: whedberg
2/28/2006

Permittee: PACIFICORP
Operator: ENERGY WEST MINING CO
Site: TRAIL MOUNTAIN MINE
Address: PO BOX 310, HUNTINGTON UT 84528
County: EMERY
Permit Type: PERMANENT COAL PROGRAM
Permit Status: ACTIVE

Current Acreages

Table with 2 columns: Value, Description. Values: 3,539.00 Total Permitted, 10.69 Total Disturbed, Phase I, Phase II, Phase III.

Mineral Ownership

- Checked: Federal, State, Fee. Unchecked: County, Other.

Types of Operations

- Checked: Underground. Unchecked: Surface, Loadout, Processing, Reprocessing.

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

The Permittee continues to meet the Special Permit Condition included as Attachment "A" of the current State permit by submitting all surface and ground water monitoring information on a quarterly basis for the Trail Mountain Mine permit area to the Division web site.

There have not been any changes in status relative to the Trail Mountain site.

The Mine is under approximately twelve inches of frozen, compacted snow.

There are no compliance actions currently pending for the Trail Mountain Mine permit area.

The Permittee will be applying for a Phase 1 lease relinquishment for the extracted areas within this site in the near future through the USDO / BLM. This application will not include the facilities area or the mains / conveyor corridor access which will be needed to mine the Cottonwood / SITLA lease tract.

Inspector's Signature:

Date Wednesday, February 15, 2006

Pete Hess, Environmental Scientist III
Inspector ID Number: 46

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
3. Reference any narratives written in conjunction with this inspection at the appropriate performance standard listed below.
4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

	Evaluated	Not Applicable	Comment	Enforcement
1. Permits, Change, Transfer, Renewal, Sale	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
2. Signs and Markers	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Topsoil	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.a Hydrologic Balance: Diversions	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.b Hydrologic Balance: Sediment Ponds and Impoundments	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.c Hydrologic Balance: Other Sediment Control Measures	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.d Hydrologic Balance: Water Monitoring	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
4.e Hydrologic Balance: Effluent Limitations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Explosives	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Disposal of Excess Spoil, Fills, Benches	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Coal Mine Waste, Refuse Piles, Impoundments	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Noncoal Waste	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Protection of Fish, Wildlife and Related Environmental Issues	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Slides and Other Damage	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
11. Contemporaneous Reclamation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
12. Backfilling And Grading	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
13. Revegetation	<input type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
14. Subsidence Control	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
15. Cessation of Operations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.a Roads: Construction, Maintenance, Surfacing	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
16.b Roads: Drainage Controls	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
17. Other Transportation Facilities	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
18. Support Facilities, Utility Installations	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
19. AVS Check	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
20. Air Quality Permit	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
21. Bonding and Insurance	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
22. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

3. Topsoil

The topsoil pile was snow covered and not capable of being inspected.

4.a Hydrologic Balance: Diversions

The site's diversions were covered by snow and not capable of being inspected.

4.b Hydrologic Balance: Sediment Ponds and Impoundments

The Permittee conducted the fourth quarter impoundment inspection for the mine site sediment impoundment on December 5, 2005. There were no unstable conditions or structural weaknesses noted by Mr. John Christensen, P.E., or Rick Cullum, Utah registered professional land surveyor, during that inspection. The Permittee's pond inspection report noted that there are approximately 0.39 Acre feet of sediment storage capacity remaining in the pond. The pond was cleaned during the fourth quarter of 2005. Mr. Christensen performed the P.E. certification of this impoundment inspection on January 6, 2006. The mine site pond was snow covered this day.

4.c Hydrologic Balance: Other Sediment Control Measures

These items were not inspectable, as they were snow covered.

4.d Hydrologic Balance: Water Monitoring

The Division notified the Permittee on January 30, 2006 that all remaining data for the third quarter of 2005 for the Trail Mountain Mine permit area had been uploaded into the OGM water database. Due to end of year vacation leave through the industry, the Division granted additional time to all Permittee's to meet the water monitoring reporting requirements for the third quarter of 2005.