

CANYON FUEL COMPANY - FOSSIL ROCK MINE

Mine Site Primary Sediment Pond Quarterly Inspection Report

Inspector Vicky Miller Date 2/12/16 (1319)

1. Dam Structural Weakness

A. Cracks or scarps on crest Yes No

B. Cracks or scarps on slope Yes No

C. Sloughing or bulging on slope Yes No

2. Major Erosion Problems Yes No

3. Surface Movements of Surrounding Slopes Yes No

4. Visible Sumps or Sinkholes in Slurry Surface Yes No

5. Clogging

A. Spillway channels and pipes Yes No

B. Decant System Yes No

CANYON FUEL COMPANY - FOSSIL ROCK MINE

Waste Rock Sediment Pond Quarterly Inspection Report

Inspector Vicky Miller Date 2-12-16 (1359)

1. Dam Structural Weakness

A. Cracks or scarps on crest Yes No

B. Cracks or scarps on slope Yes No

C. Sloughing or bulging on slope Yes No

2. Major Erosion Problems Yes No

3. Surface Movements of Surrounding Slopes Yes No

4. Visible Sumps or Sinkholes in Slurry Surface Yes No

5. Clogging

A. Spillway channels and pipes Yes No

Decant pipe was flushed 3/10/16

B. Decant System Yes No

CANYON FUEL COMPANY - FOSSIL ROCK MINE

Coal Refuse Pile Quarterly Inspection Report

Inspector Vicky Miller

Title: Environmental Engineer

Date 2/12/16 (1345)

1. Foundation Preparation (vegetation, topsoil removal?)

No new construction or placement

2. Lift Thickness (inches) No placement

3. Compaction No recent placement

4. Burning (specify extent and location) __ Yes __ No

Not Applicable

5. Angle of Slope (degrees) 18 - 27

6. Seepage (specify location, color, & appr. volume)

None observed

7. Cracks or Scarps (location and size)

None observed

8. Major Erosion Problems (location and extent)


None observed

9. Water Impounding Against Toe

Nothing observed

10. Any appearance of instability, structural weakness or other hazardous conditions

Nothing observed



Jacob D. Smith, P.E.
Registration No. 9073281
State of Utah