

0005

February 19, 1980

Inspection Memo
to Coal File:

RE: Consol
Emery Deep Mine
ACT/015/015

The Emery Deep Mine of Consol was inspected on the morning of February 6, 1980 by Joe Helfrich and Mike Thompson. The purpose of the inspection was to observe the repaired inlet to the lower sediment pond. The inlet was observed to be piping during the last inspection, November 7, 1979. Consol was written a letter in the matter requiring the inlet be repaired.

The inspectors observed that the inlet had been reshaped and lined with conveyor belting.

Consol is presently installing a sprinkler system in the berm adjacent to the creek. The purpose of the system is to promote revegetation of the berm for hydrologic protection.

The inspectors noted that the plastic pipe connecting the two ponds had been broken when the trench for the sprinkler system was dry. The broken pipe had been trimmed and made ready for necessary repairs.

K. MICHAEL THOMPSON
ENGINEERING GEOLOGIST

KMT

KMT/te

Note: For statistics see Co-op Mine memo dated February 19, 1980.

cc: O.S.M., Region V