

0013



Consolidation Coal Company
Western Region
Emery Mine
P. O. Box 527
Emery, Utah 48522

Jim
June 29, 1981

Mr. Jim Smith
Coordinator of Mined Land Development
State Department of Natural Resources
Division Of Oil, Gas, and Mining
1588 West North Temple
Salt Lake City, Utah 84116

Dear Mr. Smith,

We have resurveyed our subsidence monitoring stations in accordance with the subsidence monitoring plan for our Emery underground mine. According to our surveys, no appreciable subsidence has occurred in the past twelve months.

I have enclosed a summary comparing the elevations for the subsidence monitoring stations as determined by the initial survey (May, 1980) and our latest survey. Also enclosed is a map showing the relationship of the monitoring stations surveyed and the existing mine workings.

Sincerely,

A handwritten signature in cursive script that reads "Ronald G. Thompson".

Ronald G. Thompson
Mine Engineer
RGT/sj

RECEIVED

JUL 03

DIVISION OF
OIL, GAS & MINING

CONSOLIDATION COAL COMPANY

EMERY MINE

STATION	ELEVATION MAY 1980	ELEVATION MAY-JUNE 1981	DIFFERENCE
PP-12	5985.67	5985.67	-Ref.-
P	5941.13	5941.30	+0.17
Q	5931.15	5931.20	+0.05
N	5948.44	5948.42	-0.02
H-10	5938.07	5938.12	+0.05
H-11	5940.51	5940.52	+0.01
R	5954.09	5954.21	+0.12
PP-8	6095.98	6095.98	-Ref.-
H-3	6063.03	6063.28	+0.25
H-8	6094.90	6094.92	+0.02
H-6	6092.40	6092.27	-0.13
SMK2*	6099.91	6099.72	-0.19
K	6109.99	6110.20	+0.21
J	6128.06	6128.25	+0.19
F**	-	6099.26	-
E**	-	6079.67	-
SMK3*	6083.56	6083.94	+0.38
H-4	6076.26	6076.54	+0.28
H-1	6078.84	6079.08	+0.24

* Established and surveyed November, 1980

** Re-established and surveyed May, 1981
(original station destroyed by frost heave.)