

0011

March 15, 1985

TO: Coal File, Inspection and Enforcement Folder  
FROM: Barton Kale, Mining Field Specialist *BOK*  
RE: Consolidation Coal Company, Emery Deep Mine, ACT/015/015,  
Folder #7, Emery County, Utah

A partial inspection conducted at the above mentioned mine site by Barton Kale of the Division on February 28, 1985.

A number of concerns were addressed during this inspection although no violations were observed.

Equipment and scrap has traditionally been stored along the berm which divides the coal storage yard, across the bridge, from the creek. The operator was informed that some material mostly cable and hose were encroaching on the berm and that care should be taken that they are stored properly.

The sediment pond on the same side of the creek was inspected for recent maintenance work. The diversion ditch into the pond has been somewhat regraded (frozen soil has caused some problems) and the erosion to the ditch has been stabilized. Addition grading of the ditch is needed before the next significant precipitation event.

Two culverts toward the fan need to be cleared. They are presently functioning but blown coal dust collects at the culvert entrances.

re

cc: Donna Griffin, OSM  
Ron Thompson, Emery Deep Mine  
Sue Linner

Statistics: See Sunedco memo dated March 6, 1985  
0181-5