

0003

12-18-86

File Act/low/1015



STATE OF UTAH
NATURAL RESOURCES
Oil, Gas & Mining

Norman H. Bangerter, Governor
Dee C. Hansen, Executive Director
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

INSPECTION REPORT

INSPECTION DATE & TIME: 11/20/86, 10:00

Permittee and/or Operators Name: Consolidation Coal Company
Business Address: P. O. 527 Emery, Utah 84522
Mine Name: Emery Deep Permit Number: ACT/015/015
Type of Mining Activity: Underground Surface Other
County: Emery
Company Official (s): Ron Thompson
State Official(s): David Darby and Holland Shepherd
Partial: Complete: Date of Last Inspection: _____
Weather Conditions: Clear
Acreage: Permitted 5180 Disturbed 40 Regraded 2.7 Seeded 2.7 Bonded 247
Enforcement Action: None

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	COMMENTS
1. PERMITS	(X)	()	()	()
2. SIGNS AND MARKERS	(X)	()	()	(X)
3. TOPSOIL	(X)	()	()	()
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	(X)	()	()	()
b. DIVERSIONS	(X)	()	()	()
c. SEDIMENT PONDS AND IMPOUNDMENTS	(X)	()	()	()
d. OTHER SEDIMENT CONTROL MEASURES	(X)	()	()	()
e. SURFACE AND GROUNDWATER MONITORING	()	()	()	()
f. EFFLUENT LIMITATIONS	()	()	()	()
5. EXPLOSIVES	()	()	()	()
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	()	()	()	()
7. COAL PROCESSING WASTE	(X)	()	()	()
8. NONCOAL WASTE	(X)	()	()	()
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	()	()	()	()
10. SLIDES AND OTHER DAMAGE	(X)	()	()	(X)
11. CONTEMPORANEOUS RECLAMATION	()	()	()	()
12. BACKFILLING AND GRADING	()	()	()	()
13. REVEGETATION	()	()	()	()
14. SUBSIDENCE CONTROL	()	()	()	()
15. CESSATION OF OPERATIONS	()	()	()	()
16. ROADS				
a. CONSTRUCTION	()	()	()	()
b. DRAINAGE CONTROLS	(X)	()	()	(X)
c. SURFACING	()	()	()	()
d. MAINTENANCE	()	()	()	()
17. OTHER TRANSPORTATION FACILITIES	()	()	()	()
18. SUPPORT FACILITIES				
UTILITY INSTALLATIONS	()	()	()	()

INSPECTION REPORT
(continuation sheet)

Page 2 of 2

PERMIT NUMBER: ACT/015/015

DATE OF INSPECTION 11-20-86

(Comments are Numbered to Correspond with Topics Listed Above)

2. Signs and Markers

Some debris consisting of a couple pieces of cardboard and a few pieces of plastic had blown into the buffer zone of Quitchupah Creek at the south eastern boundary of the disturbed area across from the material and refuge storage yard. No contamination from this type of material was occurring. The operator was asked to remove the debris.

1. Noncoal Waste

Noncoal waste collected at the south east storage area was encroaching on Sedimentation Pond #3 pond. Material identified as metal, wood and plastic had not interrupted the operation of the pond, but was piling up on the ponds edge. The operator was asked to note the situation and encouraged not to let the pile extend into the pond.

16 b. Roads-Drainage Control

The western end of the culvert extending across the entrance to the upper coal storage area had been dented when a vehicle cut the corner of the driveway and ran over it. No flow was in the ditch. It was evident that flow would not be totally restricted at the time of inspection. The operator was asked to have the culvert straightened.

Copy of this Report:

Mailed to: Donna Griffin, Ron Thompson

Given to: Joe Helfrich, Sue Linner, David Darby, Holland Shepherd

Inspectors Signature and Number: *David W. Darby* 18 Date: 12-18-86