

8010



STATE OF UTAH  
NATURAL RESOURCES  
Oil, Gas & Mining

Norman H. Bangert Governor  
Dee C. Hansen, Executive Director  
Dianne R. Nielson, Ph.D., Division Director

355 W. North Temple • 3 Triad Center • Suite 350 • Salt Lake City, UT 84180-1203 • 801-538-5340

*File*

INSPECTION REPORT

Permittee and/or Operators Name: Consolidation Coal Company  
Business Address: P.O. Box 527  
Mine Name: Emeru Deep Mine Permit Number: ACT/015/015  
Type of Mining Activity:  Underground  Surface  Other  
County: Emeru  
Company Official(s): none  
State Official(s): Holland Shepherd, Dave Parby  
Inspection Date and Time: 7-22-86 11:15 - 1:30  
Partial:  Complete:  Date of Last Inspection: 6-27-86  
Weather Conditions: cloudy - warm  
Acreage: Permitted 5180 Disturbed 40 Regraded 2.66 Seeded 2.66 Bonded 247.0  
Enforcement Action: \_\_\_\_\_

COMPLIANCE WITH PERMITS AND PERFORMANCE STANDARDS

	YES	NO	N/A	Comments
1. PERMITS	( )	( )	( )	( )
2. SIGNS AND MARKERS	( )	( )	( )	( )
3. TOPSOIL	( )	( )	( )	( )
4. HYDROLOGIC BALANCE:				
a. STREAM CHANNEL DIVERSIONS	( <input checked="" type="checkbox"/> )	( )	( )	( <input checked="" type="checkbox"/> )
b. DIVERSION'S	( <input checked="" type="checkbox"/> )	( )	( )	( )
c. SEDIMENT PONDS AND IMPOUNDMENTS	( <input checked="" type="checkbox"/> )	( )	( )	( )
d. OTHER SEDIMENT CONTROL MEASURES	( <input checked="" type="checkbox"/> )	( )	( )	( )
e. SURFACE AND GROUNDWATER MONITORING	( )	( )	( )	( )
f. EFFLUENT LIMITATIONS	( )	( )	( )	( )
5. EXPLOSIVES	( )	( )	( )	( )
6. DISPOSAL OF DEVELOPMENT WASTE AND SPOIL	( )	( )	( )	( )
7. COAL PROCESSING WASTE	( )	( )	( )	( )
8. NONCOAL WASTE	( )	( )	( )	( )
9. PROTECTION OF FISH, WILDLIFE AND RELATED ENVIRONMENTAL VALUES	( )	( )	( )	( )
10. SLIDES AND OTHER DAMAGE	( )	( )	( )	( )
11. CONTEMPORANEOUS RECLAMATION	( )	( )	( )	( )
12. BACKFILLING AND GRADING	( )	( )	( )	( )
13. REVEGETATION	( )	( )	( )	( )
14. SUBSIDENCE CONTROL	( )	( )	( )	( )
15. CESSATION OF OPERATIONS	( )	( )	( )	( )
16. ROADS				
a. CONSTRUCTION	( )	( )	( )	( )
b. DRAINAGE CONTROLS	( )	( )	( )	( )
c. SURFACING	( )	( )	( )	( )
e. MAINTENANCE	( )	( )	( )	( )
17. OTHER TRANSPORTATION FACILITIES	( )	( )	( )	( )
18. SUPPORT FACILITIES AND UTILITY INSTALLATIONS	( )	( )	( )	( )

INSPECTION REPORT  
(Page 2)

Permit Number: ACT/015/015

Date of Inspection: 7-22-86

COMMENTS

(Comments are Numbered to Correspond with Topics Listed Above)

General Comments:

Two Division employees visited the mine site, during this inspection. The Division is currently undergoing a process of reorganization where other members of the technical staff, besides the inspectors, will start to assume some of the inspection responsibilities. Dave Darby, B- team Geologist, accompanied this inspector as part of the training or reorientation process.

4.a. Stream Channels:

1) The operator needs to pick up some of the plastic pipe material which has blown into the buffer zone, just east of the service road to the waste storage yard.

2) The inspectors observed the area, just south of the tippie yard, where coal fines have been blowing into the buffer zone of Christiansen Wash. This area requires attention by the operator. Accumulations of coal fines along the embankments could be cleaned out to avoid deposition into the Wash.

Copy of this Report:

Mailed to: Steve Drummond Donna Griffin  
Given to: Dave Darby Joe Beltrich Sue Linner

Inspectors Signature and Number: [Signature] # 7 8-7-86